

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA22010566/TWY3Q2**Date:** 11/01/2023REFERENCE

Handling Insurer: HL Assurance Pte Ltd

Policy No:

Claimant Vehicle No : GBL8543K**Insured Vehicle No :** SDU8208H

Date of Loss: 11/10/2022

Nature of Claim: TP

Claim No: MPC03772

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBL8543K**

Make & Model: CITROEN DISPATCH, 2.0 D L FT10 MT ABS AB 2WD 6DR (M)

Engine No: 105TCQ5001085

Reg. Date: 17/06/2022 (Man. Year: 2022)

Chassis No: VF7V1ZKXZNZ033453

Colour: Yellow

Odometer: 0 km

Engine Capacity: 100 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R16

Rear Tyre Size: 215/65 R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,318.30	1,860.30	1,458.00	43.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	1,000.00	530.00	34.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,848.30	2,860.30	1,988.00	41.00
+ GST 7.00/7.00% (S\$)	339.38	200.22	139.16	41.00
Nett Amount (S\$)	5,187.68	3,060.52	2,127.16	41.00

INSPECTION

Date of Assignment: 26/10/2022 Present Location:

ComfortDelGro Engineering Pte Ltd (Braddell)

Date Inspected: 26/10/2022 Inspected At:

ComfortDelGro Engineering Pte Ltd (Braddell)

205 Braddell Road

Singapore 579701

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Jan 2023)	
Parts:	N/A	CITROEN DISPATCH 2.0 D L FT10 MT ABS AB 2WD 6DR (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL8543K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE RH	Bent	1,920.00 FL	*1,920.00 FL
2	1		*TAILGATE RH HINGE UPPER	Not Necessary	295.00 FL	*- FL
3	1		*TAILGATE RH HINGE LOWER	Repair	295.00 FL	*- FL
4	1		*TAILGATE RH LOCK UPPER	Not Necessary	235.00 FL	*- FL
5	1		*TAILGATE RH LOCK LOWER	Not Necessary	235.00 FL	*- FL
6	1		*TAILGATE RH GLASS	Not Necessary	560.00 FL	*- FL
7	1		*DECAL 6PAX	Necessary	35.00 FL	*35.00 FL
8	1		*EMBLEM LOGO	Necessary	56.00 FL	*56.00 FL
9	1		*EMBLEM CITROEN	Necessary	56.00 FL	*56.00 FL
					Sub Total (\$\$)	3,687.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	368.70
					Total Parts (\$\$)	3,318.30

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To knock & straighten on accident area, to remove & rear refit damage parts.	New	400.00	300.00
2	To putty & respray on Rear Tailgate, Rear RH fender	New	500.00	400.00
3	To check wiring	New	80.00	0.00
4	To remove & refit RH Tailgate door trim, door lock, window metal net	New	150.00	60.00
5	To remove & refit rear Tailgate glass	New	120.00	60.00
6	To do art work for LH tailgate	New	280.00	180.00
Gross Labour Cost (\$\$)			1,530.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >