REPAIR DETAILS Reference Part Source: (Last Synchronised: 25 Oct 2022) Parts: N/A CITROEN DISPATCH 2.0 D L FT10 MT ABS AB 2WD 6DR (M) (Model not available in database) Labour: Repairer's (Price-denominated Standard List) Print Code: (Unsubmitted, no print-code for GBL8543K) Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No. Qty Part No.		Particulars	%Disc	%Depr	Amount	
1	1	*TAILGATE RH	10.00	0.00	₩ *1,920.00 FL	
2	1	*TAILGATE RH HINGE UPPER	10.00	0.00	nn ₹ *295.00 FL/h	
3	1	*TAILGATE RH HINGE LOWER	10.00	0.00	R B+X*295.00 FLph	
4	1	*TAILGATE RH LOCK UPPER	10.00	0.00	an 7 *235.00 FL	
5	1	*TAILGATE RH LOCK LOWER	10.00	0.00	~~ X *235.00 FL	
6	1	*TAILGATE RH GLASS	10.00	0.00	1 ★ *560.00 FL	
7	1	*DECAL 6PAX	10.00	0.00	*35.00 FL	
8	1	*EMBLEM LOGO	10.00	0.00	₩ *56.00 FL	
9 F=Fr	1 anchise part. L=ListIter	*EMBLEM CITROEN nDisc.	10.00	0.00	19€ *56.00 FL	
		Sub Total (S\$)			3,687.00	
		- List Item Discount on L Items (S\$)			368.70	
		Total Parts (S\$)			3,318.30	
		Report was unsubmitted during this print-ou Generated using Merimen e-Claims TEAS				

2067 10%-1860.30

Estimates on Miscellaneous Items There are no new miscellaneous items selected.

Estimates on Labour

• -									
Labour Items									
1 To !	knock & straighten on accident area, to remove & rear refit damage parts.	New	300	400.00					
	putty & respray on Rear Tailgate, Rear RH fender	New	4.00	500.00					
3 To 6	check wiring	New	49-X	80.00					
4 To 1	remove & refit RH Tailgate door trim, door lock, window metal net	New	60	150.00					
	remove & refit rear Tailgate glass	New	60.	120.00					
6 To 6	do art work for RH tailgate	New	180.	280.00					

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

Insubmitted during using Merimen e-Claims.

END OF ESTIMATES >

Taufilm 17495749 /62563761

wp. U/10/27 & Spin 1860.30
1000

1.1.1 Pary before point (2860.30)
24 days

LKK Auto Consultants hence notify

the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- Farts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is also, + 1
- · Supplementary item(s) must be esurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: