

ASS. REC. BY: Tauy

REF:

05/HLA220/0566/Twy3.

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$125K.

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBL8543K. Yr Regn: 2022, June

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Citroen Electric Dispatch cc 100KWColour: yellow A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF7V12KXZN-2033453

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim orTyre Size: F: 215/65 R12

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 26/10/22Survey held at Camford Bradelet

Des. of Damages: Fri / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

10/01/2023 Finalise P/P \$2,860.30@ 04 days (Red \$1,988.00/ 41%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Repeat Format: _____

Lump Sum / I.B.H. (f) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road

Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email: teokeejin@cdge.com.sg

TP INSURER:
UNKNOWN

HL Assurance Pte Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	11/10/2022
Vehicle Reg. No.:	GBL8543K	Driveable?	
Party At Fault:	UNKNOWN		
Driver (Insured):	NA		
Make/Model:	CITROEN DISPATCH, 2.0 D L FT10 MT ABS AB 2WD 6DR (M)	Vehicle Reg. Date:	17/06/2022
Vehicle Colour:	WHITE		
Engine No:	105TCQ5001085	Chassis No:	VF7V1ZKXZNZ033453
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)		

COST OF CLAIMS		Amount
Parts		3,318.30
Miscellaneous Items		0.00
Labour		1,530.00
Paintwork Labour		0.00
Towing		0.00
Gross Total (S\$)		4,848.30
+ GST 7.00% (S\$)		339.38
Nett Amount (S\$)		5,187.68

This claim is handled by: OI SUN PIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 25 Oct 2022)

Parts: N/A CITROEN DISPATCH 2.0 D L FT10 MT ABS AB 2WD 6DR (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBL8543K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILGATE RH	10.00	0.00	bt *1,920.00 FL
2	1		*TAILGATE RH HINGE UPPER	10.00	0.00	? *295.00 FL <i>photo</i>
3	1		*TAILGATE RH HINGE LOWER	10.00	0.00	bt *295.00 FL <i>photo</i>
4	1		*TAILGATE RH LOCK UPPER	10.00	0.00	? *235.00 FL
5	1		*TAILGATE RH LOCK LOWER	10.00	0.00	? *235.00 FL
6	1		*TAILGATE RH GLASS	10.00	0.00	? *560.00 FL
7	1		*DECAL 6PAX	10.00	0.00	na *35.00 FL
8	1		*EMBLEM LOGO	10.00	0.00	na *56.00 FL
9	1		*EMBLEM CITROEN	10.00	0.00	na *56.00 FL
Sub Total (S\$)						3,687.00
- List Item Discount on L Items (S\$)						368.70
Total Parts (S\$)						3,318.30

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items
There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

		Lab.Type	Amount
Labour Items			
1	To knock & straighten on accident area, to remove & rear refit damage parts.	New	300 400.00
2	To putty & respray on Rear Tailgate, Rear RH fender	New	400 500.00
3	To check wiring	New	x 80.00
4	To remove & refit RH Tailgate door trim, door lock, window metal net	New	60 150.00
5	To remove & refit rear Tailgate glass	New	60 120.00
6	To do art work for RH tailgate	New	180 280.00
Gross Labour Cost (S\$)			1,530.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Taufik 97495749 / 62563561
wp, 26/10/22 2pm
p/p Resy before paint
3-4 days
taufik e/khauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: