LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01 Singapore 068897 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: JANICE KOH Date: 27 Oct 2022

Preliminary Advice

Vehicle No : SME7954X Accident Date : 22/10/2022

Make : MERCEDES-BENZ 200 Policy No. : SP2002084794-01

Assignment Date : 26/10/2022 Excess : \$\$600.00 Date of Inspection : Est. Duration of Repair : 03 DAYS

Inspection At :

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,105.00
Revised Amount	:S\$	3,123.00
Check Items (Estimated)	:S\$	1,547.00
Total	:S\$	4,670.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 66,000.00 COE / PARF Rebate :S\$ 36,714.00

Salvage Value :S\$

Margin for Repair :S\$ 29,286.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
	Kindly let us have your authorisation.

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments:

The Repairer proposes Lump Sum 15%.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.