

CSG/MS22 010508/Tcy3

1) $S + RS \rightarrow SI$

N/S	O/S



AUTOMOTIVE GROUP

A Sin Ming Auto
160 Sin Ming
Singapore 57
T 6453 2121 (4
F 6459 9795 / 6
E admin@vinsa
W www.vinsautc

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/102022/5726
Policy No:	SP2002084794-01	Date of Loss:	22/10/2022
Vehicle Reg. No.:	SME7954X	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SOH YIMIN, RUTH		
Make/Model:	MERCEDES-BENZ 200, 2.0 (A)	Vehicle Reg. Date:	17/01/2015
Vehicle Colour:	WHITE		
Engine No:	27492030246508	Chassis No:	WDD2050422F063830
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	VIN'S MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	4,615.00
Miscellaneous Items	0.00
Labour	1,010.00
Paintwork Labour	480.00
Towing	0.00
Gross Total (S\$)	6,105.00
+ GST 7.00% (S\$)	427.35
Nett Amount (S\$)	6,532.35

This claim is handled by: MUHAMMAD ISWAN BIN ISHAK

Generated using Merimen e-Claims Internet Estimation & Adjusting System

AIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Oct 2022)
 Parts: 143 MERCEDES-BENZ 200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Vin's Motor Pte Ltd/SME7954X/26/10/2022 09:49
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	0.00	0.00	del ✓ 1,100.00 F
2	1		*REAR BUMPER RH PARKING SENSOR	0.00	0.00	4 ? *100.00 F
3	1		*REAR BUMPER RH SIDE RETAINER	0.00	0.00	del ✓ *40.00 F
4	10		*REAR BUMPER CLIPS	0.00	0.00	net ✓ *50.00 F 30
5	1		*REAR RH SHOCK ABSORBER	0.00	0.00	X *380.00 F
6	1		*REAR RH KNUCKLE ARM	0.00	0.00	? *820.00 F
7	1		*REAR RH KNUCKLE WHEEL BEARING	0.00	0.00	? *190.00 F
8	1		*REAR RH LOWER ARM	0.00	0.00	? *160.00 F
9	1		*REAR RH CONTROL ARM	0.00	0.00	X *110.00 F
10	1		*REAR RH TYRE	70% 0	0.00	cut ✓ *380.00 FS
11	1		*REAR RH SPORT RIM (ZR19)	0.00	0.00	cut ✓ *900.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	4,230.00
+ Margin on L,N Items 10.00% (\$\$)	385.00
Total Parts (\$\$)	4,615.00

Vin's Motor Pte Ltd/SME7954X/26/10/2022 09:49. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

ates on Miscellaneous Items
are no new miscellaneous items selected.

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1 TO SPRAY PAINTING

New 250 480.00

Labour Items

2 TO CHECK WHEEL ALIGNMENT

New 80 150.00

3 TO REMOVE AND REFIX REAR UNDERCARRIAGE

New ? 150 380.00

4 TO REPAIR DAMAGES

New 250 480.00

Gross Labour Cost (\$\$)

1,490.00

Vin's Motor Pte Ltd/SME7954X/26/10/2022 09:49. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Panglim 97495749
Not authorise
27/10/22
03 days