



Your Ref : S2M04CVE

Date: 20th March 2023

Our Ref : CS4/ASM22010570/Ucy3m4

M/s HSBC Life (Singapore) Pte Ltd

10 Marina Boulevard

#48-01 Marina Bay Financial Centre Tower 2

Singapore 018983

(The Motor Claims Department)

Attn: Khor Saw Theng

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLP 5944S
ACCIDENT ON 07/10/2022**

Instruction was received to inspect the vehicle Reg. No. SLP 5944S. The inspection was conducted on 26/10/2022 at the premises of M/s Yew Tee Automobile Tech PL, Blk 25 Kaki Bukit Road 4 #01-61 Synergy @ Kaki Bukit, Singapore 417800.

The following vehicle information was recorded:

Registration Number	: SLP 5944S
Make/Model	: Volkswagen Scirocco 2.0L AT TSI 1379W3
Year of Registration	: 2009
Body Colour	: Burnt
Chassis Number	: WWZZZ13ZAV403340
Engine Capacity	: 1984 cc

The vehicle caught fire. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 55,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 19,626.00)
Nett Liability	<u>S\$ 35,374.00</u> =====

Vehicle Inspected By:



CHUA KANG SENG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.