

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Khong Lin Hui Lynn

Date: 13 Jun 2023

**Preliminary Advice**

|                    |                                                                                                                 |                         |              |
|--------------------|-----------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SKZ7626G                                                                                                      | Accident Date           | : 24/10/2022 |
| TP Vehicle No      | : SMG6667X                                                                                                      | Assignment Date         | : 26/10/2022 |
| Make               | : TOYOTA PRIUS HYBRID                                                                                           | Est. Duration of Repair | : 16         |
| Date of Inspection | : 26/10/2022                                                                                                    |                         |              |
| Inspection At      | : TWINCAR AUTOMOTIVE PTE LTD (KAKI BUKIT)<br>BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB<br>SINGAPORE 417921 |                         |              |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |          |               |
|-----------------------------|----------|---------------|
| Repairer's Estimate (Gross) | :S\$     | 44,020.30     |
| Revised Amount              | :S\$     | 28,755.08     |
| Check Items (Estimated)     | :S\$     | 0.00          |
| Total                       | :S\$     | 28,755.08     |
| <br>Lump Sum Repair         | <br>:S\$ | <br>23,000.00 |

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.