

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TP Chin.
Xiao Chen.

BENEFIT AUTO

2 SIMS CLOSE #01-08 GEMINI@SIMS
SINGAPORE 387298

Contact : 87773233, 96907540

TAX INVOICE

Repair Code : CLM15699

Date in : 25/10/2022

Vehicle Num. : SMG6667X

Model : TOYOTA PRIUS HYBRID 1.8S CVT

Chassis/Eng# : ZVW506138643/2ZR2A94177

cf

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRBAG CONTROL UNIT <i>Activated</i>	1	1203.80	895 ✓ 1203.80
FRONT LH AIRBAG SENSOR	1	379.20	✓ 379.20
FRONT LH DOOR <i>Distorted</i>	1	1300.70	✓ 1,300.70
FRONT LH DOOR BODY WEATHER STRIP <i>wt.</i>	1	323.10	✓ 323.10
FRONT LH DOOR CHECKER <i>Not New</i>	1	183.80	x 183.80
FRONT LH DOOR FRAME BLACK STICKER (NO:1) <i>new</i>	1	23.30	✓ 23.30
FRONT LH DOOR FRAME BLACK STICKER (NO:2)	1	53.30	✓ 53.30
FRONT LH DOOR FRAME BLACK STICKER (NO:3)	1	36.30	✓ 36.30
FRONT LH DOOR GLASS CHANNEL BRACKET (FRONT) <i>Not New</i>	1	144.60	x 144.60
FRONT LH DOOR GLASS CHANNEL SEAL	1	153.60	x 153.60
FRONT LH DOOR GLASS CHANNEL SEAL BRACKET (REAR)	1	88.50	x 88.50
FRONT LH DOOR GLASS REGULATOR <i>2nd</i>	1	238.30	✓ 238.30
FRONT LH DOOR GLASS REGULATOR MOTOR <i>Not New</i>	1	926.00	x 926.00
FRONT LH DOOR HINGE (LOWER) <i>new</i>	1	110.60	x 110.60
FRONT LH DOOR HINGE (TOP)	1	97.50	x 97.50
FRONT LH DOOR INNER COVER <i>behind</i>	1	188.10	✓ 188.10
FRONT LH DOOR INNER PLASTIC SEAL COVER <i>new</i>	1	32.00	✓ 32.00
FRONT LH DOOR INNER SPEAKER <i>cracked</i>	1	226.20	✓ 226.20

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

BENEFIT AUTO
 2 SIMS CLOSE #01-08 GEMINI@SIMS
 SINGAPORE 387298

Contact : 87773233, 96907540

TAX INVOICE

Repair Code : CLM15699

Date in : 25/10/2022

Vehicle Num. : SMG6667X

Model : TOYOTA PRIUS HYBRID 1.8S CVT

Chassis/Eng# : ZVW506138643/2ZR2A94177

FRONT LH DOOR INNER TRIM BOARD	<i>cracked</i>	1	1024.10	<i>745</i> 1,024.10
FRONT LH DOOR MECHANISM LOCK	<i>Damaged</i>	1	561.90	<i>365</i> 561.90
FRONT LH DOOR MECHANISM LOCK STRIKER	<i>Not Nec</i>	1	39.30	<i>X</i> 39.30
FRONT LH DOOR OUTER HANDLE	<i>Damaged</i>	1	390.60	<i>✓</i> 390.60
FRONT LH DOOR OUTER HANDLE GASKET (FRONT)	<i>Not Nec</i>	1	16.40	<i>✓</i> 16.40
FRONT LH DOOR OUTER HANDLE GASKET (REAR)	<i>Not Nec</i>	1	16.40	<i>✓</i> 16.40
FRONT LH DOOR OUTER HANDLE INNER BRACKET	<i>Not Nec</i>	1	193.50	<i>X</i> 193.50
FRONT LH DOOR OUTER MOULDING	<i>Not Nec</i>	1	92.00	<i>X</i> 92.00
FRONT LH DOOR RUBBER GUIDE STOPPER	<i>Not Nec</i>	2	7.50	<i>X</i> 15.00
FRONT LH DOOR SCUFF PLATE GARNISH	<i>Nec</i>	1	113.50	<i>✓</i> 113.50
FRONT LH DOOR UPPER MOULDING	<i>Not Nec</i>	1	31.00	<i>X</i> 31.00
FRONT LH DOOR UPPER MOULDING RIVET	<i>Not Nec</i>	8	2.50	<i>X</i> 20.00
FRONT LH DOOR VERTICAL GARNISH	<i>Not Nec</i>	1	58.50	<i>X</i> 58.50
FRONT LH DOOR WEATHER STRIP SEAL	<i>Not Nec</i>	1	231.30	<i>✓</i> 231.30
FRONT LH SEAT AIRBAG	<i>Activated</i>	1	1008.80	<i>✓</i> 1,008.80
FRONT LH SEAT BACK COVER	<i>Not Nec</i>	1	1112.50	<i>650 (SW)</i> 1,112.50
FRONT LH SEAT BACK CUSHION	<i>Not Nec</i>	1	321.40	<i>X</i> 321.40
FRONT LH SEAT BACK FRAME	<i>Not Nec</i>	1	465.10	<i>X</i> 465.10

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

BENEFIT AUTO
 2 SIMS CLOSE #01-08 GEMINI@SIMS
 SINGAPORE 387298

Contact : 87773233, 96907540

TAX INVOICE

Repair Code : CLM15699

Date in : 25/10/2022

Vehicle Num. : SMG6667X

Model : TOYOTA PRIUS HYBRID 1.8S CVT

Chassis/Eng# : ZVW506138643/2ZR2A94177

FRONT LH WINDSCREEN PILLAR INNER TRIM COVER	<i>Nre nec</i>	1	206.10	<i>X</i>	206.10
FRONT SAFETY BELT L/R	<i>Activated</i>	2	995.10	<i>1590</i>	1990.20
LH CENTER PILLAR	<i>Distorted</i>	1	355.30	<i>✓</i>	355.30
LH CENTER PILLAR INNER PANEL	<i>Distorted</i>	1	662.90	<i>✓</i>	662.90
LH CENTER PILLAR INNER TRIM GARNISH (LOWER)	<i>Deformed</i>	1	235.30	<i>✓</i>	235.30
REAR BUMPER	<i>Repair</i>	1	556.40	<i>X</i>	556.40
REAR BUMPER SIDE RETAINER L/R	<i>ren</i>	2	117.70	<i>X</i>	235.40
REAR CROSS MEMBER	<i>Bent</i>	1	2245.20	<i>✓</i>	2,245.20
REAR KNUCKLE ARM BEARING HUB L/R	<i>engd</i>	2	725.60	<i>760</i>	1,451.20
REAR KNUCKLE ARM L/R	<i>engd</i>	2	953.60	<i>1390</i>	1,907.20
REAR LH DOOR	<i>Distorted</i>	1	1294.90	<i>✓</i>	1,294.90
REAR LH DOOR BODY WEATHER STRIP	<i>ht</i>	1	293.00	<i>✓</i>	293.00
REAR LH DOOR CHECKER	<i>Nre nec</i>	1	183.80	<i>X</i>	183.80
REAR LH DOOR FRAME BLACK STICKER (NO:1)	<i>2</i>	1	31.90	<i>✓</i>	31.90
REAR LH DOOR FRAME BLACK STICKER (NO:2)	<i>1 nec</i>	1	44.90	<i>✓</i>	44.90
REAR LH DOOR FRAME BLACK STICKER (NO:3)	<i>1</i>	1	31.90	<i>✓</i>	31.90
REAR LH DOOR FRAME MOULDING	<i>3 MP</i>	1	38.60	<i>X</i>	38.60
REAR LH DOOR GLASS CHANNEL SEAL	<i>1 nec</i>	1	122.50	<i>X</i>	122.50

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

BENEFIT AUTO
 2 SIMS CLOSE #01-08 GEMINI@SIMS
 SINGAPORE 387298

Contact : 87773233, 96907540

TAX INVOICE

Repair Code : CLM15699

Date in : 25/10/2022

Vehicle Num. : SMG6667X

Model : TOYOTA PRIUS HYBRID 1.8S CVT

Chassis/Eng# : ZVW506138643/2ZR2A94177

REAR LH DOOR GLASS CHANNEL SEAL BRACKET <i>new</i>	1	112.30	+	112.30
REAR LH DOOR GLASS REGULATOR <i>new</i>	1	226.70	✓	226.70
REAR LH DOOR GLASS REGULATOR MOTOR <i>new</i>	1	926.00	+	926.00
REAR LH DOOR HINGE (LOWER) <i>new</i>	1	87.10	+	87.10
REAR LH DOOR HINGE (TOP) <i>new</i>	1	98.90	+	98.90
REAR LH DOOR INNER PLASTIC SEAL COVER <i>new</i>	1	29.50	✓	29.50
REAR LH DOOR INNER TRIM BOARD <i>cracked.</i>	1	988.80	725 988.80	
REAR LH DOOR MECHANISM LOCK <i>Not Nec</i>	1	561.90	+	561.90
REAR LH DOOR MECHANISM LOCK STRIKER <i>Not Nec</i>	1	39.30	+	39.30
REAR LH DOOR OUTER MOULDING <i>new</i>	1	113.90	+	113.90
REAR LH DOOR RUBBER GUIDE STOPPER <i>new</i>	2	7.50	+	15.00
REAR LH DOOR SCUFF PLATE GARNISH <i>new</i>	1	113.50	✓	113.50
REAR LH DOOR UPPER MOULDING <i>new</i>	1	92.00	+	92.00
REAR LH DOOR UPPER MOULDING RIVET <i>new</i>	7	2.50	+	17.50
REAR LH DOOR VERTICAL GARNISH <i>new</i>	1	66.50	+	66.50
REAR LH DOOR VERTICAL RUBBER SEAL <i>new</i>	1	34.30	+	34.30
REAR LH DOOR WEATHER STRIP <i>cut</i>	1	180.10	✓	180.10
REAR LH FENDER <i>cracked.</i>	1	871.60	✓	871.60

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

BENEFIT AUTO

2 SIMS CLOSE #01-08 GEMINI@SIMS
 SINGAPORE 387298

Contact : 87773233, 96907540

TAX INVOICE

Repair Code : CLM15699

Date in : 25/10/2022

Vehicle Num. : SMG6667X

Model : TOYOTA PRIUS HYBRID 1.8S CVT

Chassis/Eng# : ZVW506138643/2ZR2A94177

REAR LH FENDER INNER ARCH PANEL <i>Pr</i>	1	343.40	X	343.40
REAR LH FENDER INNER SHIELD <i>3 pr</i>	1	139.80	X	139.80
REAR LH FENDER QUARTER GARNISH <i>3 pr</i>	1	207.00	X	207.00
REAR LOWER ARM L/R <i>Best.</i>	2	497.50	✓	995.00
REAR RH DOOR INNER TRIM BOARD <i>as found</i>	1	988.80	725 988.80	
REAR SAFETY BELT L/R <i>Activated</i>	2	995.10	1510 1,990.20	
REAR SHOCK ABSORBER L/R <i>R# Best</i>	2	127.00	127 254.00	
REAR SPORT RIM L/R <i>wt.</i>	2	1879.40	1800 (wt) 3,758.80	
REAR STABILIZER BAR <i>3 pr</i>	1	295.70	X	295.70
REAR STABILIZER BAR LINKAGE <i>3 pr</i>	1	179.10	X	179.10
REAR STAY ARM L/R <i>3 Best</i>	2	239.20	✓	478.40
REAR TRAILING ARM L/R	2	370.40	✓	740.80
REAR UPPER ARM L/R <i>Best.</i>	2	420.80	✓	841.60
ROOF TOP LH ARIBAG	1	1748.10	✓	1,748.10
ROOF TOP LH ARIBAG IMPACT SENSOR <i>Activated</i>	2	567.80	590 1,135.60	
ROOF TOP LINING <i>crushed</i>	1	2125.70	1850 2,125.70	
ROOF TOP LINING LH HANDLE GRIP <i>the new</i>	2	55.80	X	111.60
ROOF TOP LINING SOUND PROOF PAD (FRONT) <i>the new</i>	1	49.30	X	49.30

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

BENEFIT AUTO
 2 SIMS CLOSE #01-08 GEMINI@SIMS
 SINGAPORE 387298

Contact : 87773233, 96907540

TAX INVOICE

Repair Code : CLM15699

Date in : 25/10/2022

Vehicle Num. : SMG6667X

Model : TOYOTA PRIUS HYBRID 1.8S CVT

Chassis/Eng# : ZVW506138643/2ZR2A94177

ROOF TOP LINING SOUND PROOF PAD (REAR) <i>new</i>	1	28580.10	49.30	<i>X</i> 49.30
SIDE SKIRT GARNISH L/R <i>LH Deland, RH Deland</i>	2	21435.07	1003.20	<i>1310</i> 2,006.40
Subtotal before discount				46,320.40
Percentage discount 25%				11,580.10
Sub-total 1				34,740.30
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1		50.00	<i>30.</i> 50.00
FRONT LH DOOR RUBBER MOULDING <i>Not new</i>	1		80.00	<i>X</i> 80.00
FRONT LH DOOR SCUFF PLATE CLIPS - SET <i>new</i>	1		30.00	<i>20.</i> 30.00
FRONT LH WINDSCREEN PILLAR INNER TRIM COVER CLIPS - SET <i>new</i>	1		30.00	<i>X</i> 30.00
LH CENTER PILLAR INNER TRIM GARNISH CLIPS - SET <i>new</i>	1		30.00	<i>20.</i> 30.00
LH CENTER PILLAR STICKER <i>new</i>	1		80.00	<i>30.</i> 80.00
REAR BUMPER CLIPS - SET <i>new</i>	1		50.00	<i>X</i> 50.00
REAR LH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1		50.00	<i>30.</i> 50.00
REAR LH DOOR RUBBER MOULDING <i>new</i>	1		80.00	<i>X</i> 80.00
REAR LH DOOR SCUFF PLATE CLIPS - SET <i>new</i>	1		30.00	<i>20.</i> 30.00
REAR LH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1		50.00	<i>X</i> 50.00
REAR LH FENDER QUARTER GARNISH CLIPS - SET <i>new</i>	1		20.00	<i>X</i> 20.00
REAR RH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1		50.00	<i>30.</i> 50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

BENEFIT AUTO
2 SIMS CLOSE #01-08 GEMINI@SIMS
SINGAPORE 387298

Contact : 87773233, 96907540

TAX INVOICE

Repair Code : CLM15699

Date in : 25/10/2022

Vehicle Num. : SMG6667X

Model : TOYOTA PRIUS HYBRID 1.8S CVT

Chassis/Eng# : ZVW506138643/2ZR2A94177

REAR TYRE L/R	2	240	450.00	X	900.00
SIDE SKIRT GARNISH CLIPS L/R - SET	2		80.00	60	160.00
Subtotal before discount					1,690.00
Percentage discount 0%					0.00
Sub-total 2					1,690.00
Parts-total					36,430.30

LABOUR

To remove, change air bag, air-bag sensor, air-bag wire and resetting system.

To reset system after repair works

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

To remove, reinstall brake parts, brake line, brake pump and bleeding brake system.

To road test driving, check and resetting wheel alignments system.

To remove, reinstall petrol tank. (to FR)

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To remove front seat, dismantle. (Allowing to repair, align seat rest frame and seat base.)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

350 500.00
180 400.00
60 60.00
480 600.00
X 100.00
80 100.00
80 100.00
200 250.00
120 200.00
160 160.00
1400 2,200.00
1400 2,800.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

BENEFIT AUTO
2 SIMS CLOSE #01-08 GEMINI@SIMS
SINGAPORE 387298

Contact : 87773233, 96907540

TAX INVOICE

Repair Code : CLM15699

Date in : 25/10/2022

Vehicle Num. : SMG6667X

Model : TOYOTA PRIUS HYBRID 1.8S CVT

Chassis/Eng# : ZVW506138643/2ZR2A94177

To apply anti-rust chemical on repaired and replaced panel.

	4630	✓ 120.00
Labour Total		7,590.00
Parts & Labour Total		44,020.30

*** This is a computer-generated document which requires no signature.***

page 8

total: 28755.07

n/s: 23k.

16 Days

23k.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: