

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJR78547

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

C 422N
Vehicle: IN / OUT

LTA 920481

Veh No:

SJR 78547

Yr Regn:

14/07/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Suzuki Swift

c.c

1328

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp Reading

174701

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JSAE2C11500550654

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/70-214 35

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kopser

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

22/10/22

D.O.I.

26/10/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

we until 13-07-2029 dep sk

3/12/22 4/5 @ 5600 inland MR Lee

Date/Time, File Pass to?



Preli. Report

Days Of Repair:

1)



Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

T K LEE AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47
 AUTOBAY SINGAPORE 417883
 Tel : 6509 5521 / 65095524 Fax : 6509 5523
 Email: Tklee0247@gmail.com

Not Allowed
 hr
 26/10/22
 1/5 \$5600
 6 days.

Vehicle Number: SJR7854T

Vehicle Model: SUZUKI SWIFT

PARTICULAR		AMOUNT	
QTY			SS
	<u>LIST PRICE</u>		
1	TAILGATE	Body 22 745.00	\$ 1,011.55 ✓
1	TAILGATE EMBLEM 'S'	111 40	\$ 68.05 ✓
1	TAILGATE EMBLEM 'SWIFT'	111	\$ 68.85 ✓
1	TAILGATE OUTER HANDLE	Cre 148	\$ 190.65 ✓
1	TAILGATE INNER LOCK	Surf 105	\$ 180.95 ✓
1	TAILGATE INNER TRIM BOARD	De/Cre 182	\$ 441.35 ✓
1	TAILGATE WIPER MOTOR	111	\$ 280.95 X
1	TAILGATE W/STRIP	111 155	\$ 181.35 ✓
2	TAILGATE HINGES @\$65.50	111	\$ 131.00 X
2	TAILGATE DAMPER @\$141.50	111	\$ 283.00 X
2	TAILGATE STOPPER @\$10.50	111	\$ 21.00 X
2	TAILLAMPS -R/L @\$361.75	Cre 260x2=520	\$ 723.50 ✓
2	TAILLAMP PANELS -R/L @\$110.25	111	\$ 220.50 X
1	REAR BUMPER	Dis 769.50	\$ 891.65 ✓
2	REAR BUMPER BRACKETS -R/L @\$98.85	Surf 115	\$ 197.70 1pc
2	REAR BUMPER SIDE RETAINERS @\$68.50	Surf 35x2=70	\$ 137.00 ✓
1	REAR END PANEL	Body 22 380	\$ 445.35 ✓
1	REAR END PANEL TRIM	111 115	\$ 160.25 ✓
1	REAR END PANEL AIR VENT	Cre	\$ 86.65 ✓
1	REAR EXHAUSR SILENCER	111	\$ 520.65 X
2	REAR EXHAUST MOULDINGS @\$18.50	111	\$ 37.00 X
1	REAR EXHAUST INSULATOR	Surf	\$ 90.50 ✓
1	REAR FENDER -LH	111	\$ 690.95 X
1	REAR FENDER INNER SHIELD	111	\$ 131.20 X
1	REAR FENDER INNER TRIM	De/111	\$ 180.90 ✓
1	REAR FENDER INNER GARNISH	111	\$ 191.65 X
1	REAR FLOOR BOARD top	7051	\$ 310.75 ✓
1	REAR FLOOR COMPARTMENT PANEL	crumpled 13uc	\$ 599.65 ✓
1	REAR SIDE CHASSIS MEMBER	111	\$ 460.50 X
1	REAR SMART KEYLESS ANTENNA	111	\$ 160.95 X
2	REAR LICENSE LAMPS @\$41.50	111	\$ 83.00 X
			\$ 9,179.00
		LESS 15%	\$ 1,376.85
			\$ 7,802.15

T K LEE AUTOMOTIVE PTE.LTD

Vehicle Number: SJR7854T

Vehicle Model: SUZUKI SWIFT

SPECIAL NETT ITEMS

1	(SET) TAILGATE GLASS SEALANT	<i>neu</i>	\$	80.00	<i>40</i>
1	(SET) TAILGATE GLASS FOAM TAPE	<i>neu</i>	\$	65.00	<i>40</i>
1	(SET) REAR BUMPER CLIP	<i>neu</i>	\$	45.00	<i>30</i>
1	(SET) REAR REVERSE SENSOR	<i>shock</i>	\$	280.00	<i>200</i>
1	REAR NUMBER PLATE	<i>one</i>	\$	40.00	<i>15</i>
			\$	510.00	

LABOUR CHARGES

TO REMOVE & REPLACE TAILGATE GLASS	\$	180.00	<i>120</i>
TO CHECK REAR ELECTRICAL WIRING	\$	50.00	<i>30</i>
TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	\$	120.00	<i>80</i>
TO REMOVE, REPLACE REVERSE SENSOR	\$	60.00	<i>50</i>
TO REMOVE, REPLACE EXHAUST	\$	100.00	<i>60</i>
TO TUFF KOTE	\$	120.00	<i>90</i>
TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	\$	1,200.00	<i>1100</i>
TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	\$	1,600.00	<i>1200</i>
		\$	3,430.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL :

\$ 11,742.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-4665.65
152
3965.80
325
2730
7020.8