



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |                 |                           |  |
|--|--|-----------------|---------------------------|--|
| LIBERTY INSURANCE PTE LTD<br>51 CLUB STREET, #03-00<br>LIBERTY HOUSESINGAPORE 069428   |  |                 | Ref: CS/LIP22010578/Tqce2 |  |
|  |  |                 | Date: 18/01/2023          |  |
|  |  |                 | Code: LIP                 |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |  |                 |                           |  |
| Insured Veh.   | YP 5105T   | Veh. Inspected  | PC 6555X                  |  |
| Policy No.   |  | Coverage (\$)   | 0.00                      |  |
| Claim No.  | IVS22/1795   | Excess (\$)     | 0.00                      |  |
| Assign From  | ANDY SEAH  | Assign Date     | 26/10/2022                |  |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |                 |                           |  |
| Make & Model   | KING LONG XMQ6   | c.c             | 8849                      |  |
| Engine No.   | HIDDEN   | Year of Reg.    |                           |  |
| Chassis No.  | LA6R1HSG1AB103209  | Colour          | BLUE                      |  |
| Odometer   | 568590 KM  | Steering        | IN ORDER                  |  |
| Brakes   | IN ORDER   | Modification    | NIL                       |  |
| General  | GOOD   |                 |                           |  |
| <b>3. Conditions of Tyres</b>  |  |                 |                           |  |
|  | Size   | Make            | Balance                   |  |
| R/H Front Tyre   | 11 R22.5   | FIREMAX         | 8 mm                      |  |
| L/H Front Tyre   | 11 R22.5   | FIREMAX         | 8 mm                      |  |
| R/H Rear Tyre  | 11 R22.5 (D)   | FIREMAX         | 8/8 mm                    |  |
| L/H Rear Tyre  | 11 R22.5 (D)   | FIREMAX         | 8/8 mm                    |  |
| <b>4. Description of Damages</b>   |  |                 |                           |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.<br>DAMAGES SEE DETAILS.   |  |                 |                           |  |
| <b>5. General Information</b>  |  |                 |                           |  |
| Accident Date  | 19/10/2022   | Inspection Date | 26/10/2022                |  |
| Survey held at   | THE ONE HOLDINGS PTE LTD<br>8 WOODLANDS INDUSTRIAL PARK E3 WOODLANDS INDUSTRIAL PARK E<br>SINGAPORE 757786 |                 |                           |  |
| <b>5a. Remarks</b>   |  |                 |                           |  |
| A)REGISTRATION DATE: 25 APR 2011<br>B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                 |                           |  |
| <b>5b. Estimate Days of Repair</b>   |  |                 |                           |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |  |                 | 3 Working Days            |  |