

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: Fax: Email:

INSURER : AXA INSURANCE SINGAPORE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	
Policy No:	5122324542-01	Date of Loss:	17/10/2022
Vehicle Reg. No.:	FBD8982T	Driveable?	yes
Driver Age:		Third Party Vehicle No.:	SHC3623Y
Any Injuries?	yes	Contact No:	
Insured/Claimant:	EMELDA NATASHA ADANAN	Driver:	EMELDA NATASHA ADANAN

PARTS MODEL

Make/Model:	Yamaha, T135	Vehicle Reg. Date:	03/09/2009
Vehicle Colour:		Engine Number:	
Chassis No:	5YP011015	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

DESCRIPTION OF ACCIDENT/LOSS

Description of Accident/loss Collision - Head to Rear
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	3,357.90
Miscellaneous Items	435.00
Labour	310.00
Paintwork Labour	250.00
Towing	0.00
Gross Total(\$):	4,352.90
GST 7.00%(\$):	304.70
Nett Amount(\$):	4,657.60

This claim is handled by: Sky Toh T C

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT FENDER / CVT	170.00	-10.00	153.00 ✓
2	1	FRONT BRAKE LEVER RH / CVT	28.00	-10.00	25.20 ✓
3	1	FRONT BALANCER RH / CVT	12.00	-10.00	10.80 ✓
4	1	FRONT SIDE MIRROR RH / CVT	80.00	-10.00	72.00 ✓
5	1	FRONT TOP HEADLAMP X NN	410.00	-10.00	369.00
6	1	FROTN SIDE LAMP RH X NN	310.00	-10.00	279.00
7	1	FRONT TOP FAIRING RH / CVT	330.00	-10.00	297.00 ✓
8	1	FROTN BOTTOM FAIRING RH / CVT	360.00	-10.00	324.00 ✓
9	1	FRONT FOOT BRAKE RH / BT	45.00	-10.00	40.50 ✓
10	1	FRONT FOOT REST RH / Tn	40.00	-10.00	36.00 ✓
11	1	FRONT FOOT REST BRACKET RH / BT	120.00	-10.00	108.00 ✓
12	1	REAR EXHAUST PIPE / CVT	780.00	-10.00	702.00 ✓
13	1	REAR EXHAUST PIPE OUTER CHROME COVER RH / CVT	180.00	-10.00	162.00 ✓
14	1	REAR EXHAUST PIPE OUTER FRONT COVER RH / CVT	120.00	-10.00	108.00 ✓
15	1	REAR FAIRING RH / CVT	280.00	-10.00	252.00 ✓
16	1	REAR TAILLAMP 1 X NN	466.00	-10.00	419.40
Total Parts (S\$)					3,357.90

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR FAIRING STICKER RH / BT	70.00	0.00	70.00
2	1	REAR BOX / CVT	260.00	0.00	260.00
3	1	REAR BOX BRACKET (1 SET) / BT	70.00	0.00	70.00
4	1	REAR NUMBER PLATE / BT	35.00	0.00	35.00
Sub Total (S\$)					435.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00 ✓
2	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	280.00	0.00	280.00 250
Gross Labour Cost (S\$)					310.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and	250.00	0.00	250.00 240

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
-----	-----	-------------	--------	-------	------------

Waxing are also available.

Gross Labour Cost (\$\$) 250.00

< END OF ESTIMATES >

Steve (LKK) 83228813

25/10/22, 5-30pm

m l

L/S

M AL y

3 L/S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: