



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:GARNET		Ref: CC4/ASM22010585/Epa3q2 Date: 14/07/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 3623Y	Veh. Inspected	FBD 8982T
Policy No.	P2465679	Coverage (\$)	0.00
Claim No.	S2M04D2W	Excess (\$)	0.00
Assign From		Assign Date	25/10/2022
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA T135	c.c	135
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	5YP011015	Colour	BLACK
Odometer	73437 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	70/80-17	YOKOHAMA	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90-17	YOKOHAMA	4 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION & O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/10/2022	Inspection Date	25/10/2022
Survey held at	YEW TEE AUTOMOBILE TECH PL (HQ) 39 WOODLANDS CLOSE, #01-12, SINGAPORE 737854		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	