

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Lim

Date: 27 Oct 2022

**Preliminary Advice**

Vehicle No	: SJL1749K	Accident Date	: 22/10/2022
Make	: VOLKSWAGEN GOLF	Policy No.	: SP2000706520
Assignment Date	: 27/10/2022	Excess	: S\$0.00
Date of Inspection	: 26/10/2022	Est. Duration of Repair	: 12
Inspection At	: <b>Volkswagen Centre Singapore</b>		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,324.54
Revised Amount	:S\$	12,968.03
Check Items (Estimated)	:S\$	5,126.51
Total	:S\$	18,094.54
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	32,370.00
Salvage Value	:S\$	
Margin for Repair	:S\$	35,630.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Part by part repair as repairer is agent workshop

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .