

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation
Non binding - Preview

Page 1/3

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Ms.
NG
SAN SAN
267 TAMPINES STREET 21
#11-17
Singapore 520267

Document no.
Document date 25-10-2022
Customer no. 5211052769
Customer GST-ID 201903913C
Dealer 30001
Job order number 2022031069/ 1
Job order date 25-10-2022
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SJL1749K	5G13HZ	26-01-2017	WVWZZZAUZHW121987	Golf 1.4 CLBM 92 TSI D7F	105,315

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	200.00	214.00
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	360.00	385.20
9801B001	R&R FRT SEAT BELT				#1	560.00	599.20
5G4857705N RAA	Three-Point Automatic Sea SEAT BELT LH	1	pcs.	1,054.64	28.00%	759.34	812.49
5G4857706N RAA	Three-Point Automatic Sea SEAT BELT RH	1	pcs.	1,054.64	28.00%	759.34	812.49
WHT003682	Bolt With Polygon Socket	2	pcs.	7.21	28.00%	10.38	11.11
N 98924301	Socket Hd. Screw With Pol	2	pcs.	7.34	28.00%	10.57	11.31
N 98926001	Socket Hd. Screw With Pol	2	pcs.	6.63	28.00%	9.55	10.22
8V0857819 (photo)	Seat Belt Height Adjuster	2	pcs.	124.00	28.00%	178.56	191.06
N 10572403	Bolt	2	pcs.	4.35	28.00%	6.26	6.70
5G6827025AA	Rear Trunk Lid	1	pcs.	2,550.09	28.00%	1,836.06	1,964.58
D 169300M2	1k Window Adhesive	2	pcs.	51.44	28.00%	74.07	79.25
D 00940104	All Purpose Cleaner	1	pcs.	102.88	28.00%	74.07	79.25
D 00920002	Primer	1	pcs.	30.27	28.00%	21.79	23.32
D 181802M1	Activator	1	pcs.	26.27	28.00%	18.91	20.23
D 00950025	Applicator	2	pcs.	11.16	28.00%	16.07	17.19
5G6827505B 9B9	Hood Latch Satin Black BOOT LID LOCK	1	pcs.	266.89	28.00%	192.16	205.61
5G6827705E	Gasket BOOT LID WETHERSTRIP	1	pcs.	299.42	28.00%	215.58	230.67
5G0827469F FOD	Oper.Mechan.With Micro Sw	1	pcs.	2,107.78	28.00%	1,517.60	1,623.83
510827861A	Water Drain Hose	1	pcs.	9.54	28.00%	6.87	7.35
5G6867605E 82V	Trim Panel For Hatch Gate BOOT LID TRIM COVER	1	pcs.	188.91	28.00%	136.02	145.54
5G0853687 2ZZ	Inscription Bright Chrome NAME PLATE - GOLF	1	pcs.	89.77	28.00%	64.63	69.15
5G0853675AT2ZZ	Inscription Bright Chrome NAME PLATE - 230 TSI	1	pcs.	81.11	28.00%	58.40	62.49
5G0945087B (photo)	Additional Brake Light Wi 3RD BRAKELIGHT	1	pcs.	183.08	28.00%	131.82	141.05
5G0945093AD	Taillight LHS TAILLIGHT INNER	1	pcs.	317.12	28.00%	228.33	244.31
5G0945094AD	Taillight With Rear Fog L RHS TAILLIGHT INNER	1	pcs.	317.12	28.00%	228.33	244.31
5G6807417APGRU	Cover For Bumper Primed	1	pcs.	1,417.50	28.00%	1,020.60	1,092.04
5G0998492 GRU	1 Set Sensor Brackets Pri	1	pcs.	25.72	28.00%	18.52	19.82
5G0919491	Sensor Bracket	2	pcs.	16.92	28.00%	24.36	26.07
5G0919491A	Sensor Bracket	1	pcs.	16.92	28.00%	12.18	13.03
5G0919492A	Sensor Bracket	1	pcs.	16.92	28.00%	12.18	13.03
5Q0919275B GRU	Sensor Primed	2	pcs.	190.18	28.00%	273.86	293.03
5Q0919133 9B9	Seal Ring Satin Black	2	pcs.	1.46	28.00%	2.10	2.25
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	85.94	28.00%	61.88	66.21

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation
Non binding - Preview

Page 2/3

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Ms.
NG
SAN SAN
267 TAMPINES STREET 21
#11-17
Singapore 520267

Document no.
Document date 25-10-2022
Customer no. 5211052769
Customer GST-ID 201903913C
Dealer 30001
Job order number 2022031069/ 1
Job order date 25-10-2022
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SJL1749K	5G13HZ	26-01-2017	WVWZZZAUZH121987	Golf 1.4 CLBM 92 TSI D7F	105,315

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
D 822150A1	Bonding Agent For Plastic	1	pcs.	68.85	28.00% #1	49.57	53.04
5G6807568D 9B9	Rear Diffusor Satin Black	1	pcs.	361.39	28.00% #1	260.20	278.41
WHT005263	Rivet	4	pcs.	1.32	28.00% #1	3.80	4.07
5G0807305D	Bumper REINFORCEMENT	1	pcs.	750.84	28.00% #1	540.60	578.44
5G6807863C	Attachment Strip BUMPER CTR BRACKET	1	pcs.	73.18	28.00% #1	52.69	56.38
5G6807393A	Guide Piece LHR BUMPER BRACKET (UPPER)	1	pcs.	43.33	28.00% #1	31.20	33.38
5G6807394A	Guide Piece RHR BUMPER BRACKET (UPPER)	1	pcs.	43.33	28.00% #1	31.20	33.38
5G6807393	Guide Piece LHR BUMPER BRACKET (SIDE)	1	pcs.	43.33	28.00% #1	31.20	33.38
5G6807394	Guide Piece RHR BUMPER BRACKET (SIDE)	1	pcs.	43.33	28.00% #1	31.20	33.38
1K8943021	License Plate Light	2	pcs.	44.37	28.00% #1	63.89	68.36
8K0973702	Flat Contact Housing With NAMBER PLATE LIGHT WIRE HOUSING	2	pcs.	12.39	28.00% #1	17.84	19.09
5G0945105	Reflector LH	1	pcs.	81.02	28.00% #1	58.33	62.41
5G0945106	Reflector RH	1	pcs.	81.02	28.00% #1	58.33	62.41
5G6813301D	Rear Apron REAR END PANEL INNER	1	pcs.	827.48	28.00% #1	595.79	637.50
5G6807126B	Bracket For Bumper	1	pcs.	14.74	28.00% #1	10.61	11.35
5G6813309	End Plate END PANEL OUTER	1	pcs.	212.15	28.00% #1	152.75	163.44
D 007500A2	Zinc Spray	1	pcs.	72.86	28.00% #1	52.46	56.13
D 180003M2	2k-Body Adhesive	1	pcs.	469.52	28.00% #1	338.05	361.71
D 476KD1M2	Sealant Can Be Sprayed	1	pcs.	66.78	28.00% #1	48.08	51.45
WHT005560	Speed Nut	5	pcs.	1.80	28.00% #1	6.48	6.93
N 91017602	Weld Stud	8	pcs.	1.14	28.00% #1	6.57	7.03
5G6863459K 82V	Cover For Lock Carrier Ti END PANEL TRIM COVER	1	pcs.	141.51	28.00% #1	101.89	109.02
5G6858855F CA9	Cargo Platform Black SPARE WHEEL COVER	1	pcs.	443.33	28.00% #1	319.20	341.54
5G6858831 82V	Mounting Titanium Black SPARE WHEEL COVER BRACKET LH	1	pcs.	59.88	28.00% #1	43.11	46.13
5G6858832 82V	Mounting Titanium Black SPARE WHEEL COVER BRACKET RH	1	pcs.	59.88	28.00% #1	43.11	46.13
1K0803899D	Bolt For Spare Wheel Moun	1	pcs.	24.34	28.00% #1	17.52	18.75
5Q0825701E	Heat Shield For Exhaust M LABOUR	1	pcs.	164.55	28.00% #1	118.48	126.77
	SPRAY PAINT	1	pcs.	560.00	28.00% #1	4,480.00	4,793.60
	R&R REAR W/SCREEN	1	pcs.	530.00	28.00% #1	4,240.00	4,536.80
	TRANSFER BOOT LID MECHANISM	1	pcs.	560.00	28.00% #1	560.00	599.20
	R&R REAR LUGGAGE TRIM	1	pcs.	560.00	28.00% #1	560.00	599.20

* end part repkd + 4 days

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 3/3

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Ms.
NG
SAN SAN
267 TAMPINES STREET 21
#11-17
Singapore 520267

Document no.
Document date 25-10-2022
Customer no. 5211052769
Customer GST-ID 201903913C
Dealer 30001
Job order number 2022031069/ 1
Job order date 25-10-2022
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SJL1749K	5G13HZ	26-01-2017	WVWZZZAUZHW121987	Golf 1.4 CLBM 92 TSI D7F	105,315

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	R&R REAR EXHAUST PIPE	1	pcs.	560.00	#1	560.00	599.20
	REAR WATER LEAK TEST	1	pcs.	100.00	#1	100.00	107.00
	RAER NUMBER PLATE	1	pcs.	80.00	#1	80.00	85.60
	ALLIANZ OD/RECOVERY DOA: 22/10/2022 EXCESS: SURVEY BY:						

Quotation valid till 01-11-2022

Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#1	1,120.00	22,204.54	4,302.93	7%	1,632.72	4,302.93	23,324.54	24,957.26
Total	1,120.00	22,204.54	4,302.93		1,632.72	4,302.93	23,324.54	24,957.26

Stew CLKK)
26/10/22, 1.30pm

Customer

90-L1 NL
Excess ?

Service Advisor

P/P

M. B. L. L.

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

8 days (not include end of 4 days)

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: