



FALCON-AIR

LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE 199555
ATTENTION: GERALD POH

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62962706

Page 1/3
FALCON-AIR AUTO SERVICES PTE LTD
Co. Reg. No : 199501140D
GST Reg. No. 199501140D

Estimate : ES012492

Date : 26/10/2022
Vehicle Num. : GBC 9608Z
Make/Model : RENAULT KANGOO II EXPRESS-2013/2
Chassis/Eng# : VF1FW1UBA50248383
Accident Date : 21/10/2022
Claim No. :
Reference : O/D
Policy No. : Z22VC05010613

S/N	Quantity	Particular	Unit Price	Amount S\$
PARTS PURCHASED :				
1.	1 PC	REAR BUMPER	380.00	air
2.	1 PC	TAILLAMP LOWER GARNISH	250.00	air
3.	1 PC	RH REAR WHEEL HUB CAP	120.00	air
4.	1 PC	RH SLIDING DOOR	750.00	air
5.	1 PC	RH SLIDING DOOR PROTECTOR PAD	115.00	air
6.	1 PC	RH SLIDING DOOR OUTER HANDLE	135.00	air
7.	1 PC	RH FRONT DOOR	1,800.00	air
8.	1 PC	RH FRONT DOOR PILLAR A	1,300.00	?
9.	1 PC	RH FRONT DOOR HINGE (TOP)	200.00	?
10.	1 PC	RH FRONT DOOR HINGE (BOTTOM)	200.00	?
11.	1 PC	RH FRONT DOOR PROTECTOR PAD	130.00	air
12.	1 PC	RH FRONT DOOR OUTER HANDLE	140.00	air
13.	1 PC	RH FRONT DOOR INNER LOCK	430.00	?
14.	1 PC	RH FRONT DOOR GLASS	380.00	air
15.	1 PC	RH FRONT DOOR GLASS OUTER MOULDING	280.00	?
16.	1 PC	RH FRONT DOOR GLASS CHANNEL RUBBER	280.00	air
17.	1 PC	RH SIDE MIRROR BASE	380.00	air
18.	1 PC	RH SIDE MIRROR GLASS	130.00	air
19.	1 PC	RH SIDE MIRROR BACK COVER	170.00	air
20.	1 PC	RH FRONT FENDER	345.00	air
21.	1 PC	RH FRONT FENDER LAMP	160.00	air
22.	1 PC	RH FRONT FENDER UNDERSHIELD	180.00	?

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON-AIR

LONPAC INSURANCE BHD

300 BEACH ROAD #17-04/07

THE CONCOURSE 199555

ATTENTION: GERALD POH

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62962706

FALCON-AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

Estimate : ES012492

Date : 26/10/2022

Vehicle Num. : GBC 9608Z

Make/Model : RENAULT KANGOO II EXPRESS-2013/2

Chassis/Eng# : VF1FW1UBA50248383

Accident Date : 21/10/2022

Claim No. :

Reference : O/D

Policy No. : Z22VC05010613

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1 PC	RH FRONT STEEL RIM		240.00 <i>bt</i>
24.	1 PC	RH FRONT WHEEL HUB CAP		120.00 <i>ext</i>
25.	1 PC	RH FRONT SHOCK ABSORBER		155.00 ?
26.	1 PC	RH FRONT SHOCK ABSORBER TOP MOUNTING		70.00 ?
27.	1 PC	RH FRONT SHOCK ABSORBER TOP BEARING		60.00 ?
28.	1 PC	RH FRONT SHOCK ABSORBER COVER		65.00 ?
29.	1 PC	RH FRONT KNUCKLE ARM		750.00 ?
30.	1 PC	RH FRONT WHEEL BEARING HUB		130.00 ?
31.	1 PC	RH FRONT LOWER ARM		200.00 ?
32.	1 PC	RH FRONT STABILIZER BAR		380.00 ?
33.	1 PC	RH FRONT STABILIZER BAR LINK		155.00 ?
34.	1 PC	RH HEADLAMP		550.00 <i>ext</i>
35.	1 PC	RADIATOR SUPPORT PANEL	<i>pluto</i>	550.00 <i>ext</i>
36.	1 PC	RH REAR FENDER		2,000.00 <i>Rp</i>
Total Parts Purchased S\$:				13,680.00
15.00% Of The Above Parts S\$:				2,052.00
Based On Cost Plus S\$:				15,732.00
SPECIAL NETT ITEMS :				
1.	1 PC	RH FRONT DOOR COMPANY NAME STICKER		50.00 <i>ext</i>
2.	1 PC	RH FRONT TYRE		140.00 ?
3.	1 PC	SEALANT		<i>to</i> 45.00 <i>ext</i>

CONTINUE / ...

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140DLONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE 49655R
ATTENTION: GERALD POH

Attention: Motor Claim Department

Contact: 62507388 Fax No.: 62962706

Estimate: ES012492

Date: 26/10/2022
Vehicle Num.: GBC 9608Z
Make/Model: RENAULT KANGOO II EXPRESS-2013/2
Chassis/Eng#: VF1FW1UBA50248383
Accident Date: 21/10/2022
Claim No.:
Reference: O/D
Policy No.: Z22VC05010613

S/N	Quantity	Particular	Unit Price	Amount S\$
4.	10 PCS	RH FRONT FENDER CLIP	8.00	80.00 ⁶⁰
5.	1 SET	ASSORTED CLIPS		80.00 ³⁰⁰⁰
Special Nett Total S\$:				395.00 ³⁰⁰⁰
LABOUR:				
TO REMOVE/REFIT RH SLIDING DOOR GLASS				100.00 ⁸⁰
TO CHECK WIRING AND RE-FOCUS HEADLAMP				50.00 ³⁰
COMPUTERISE WHEEL ALIGNMENT				120.00 ⁸⁰
TO TRANSFER FRONT DOOR MECHANISM				100.00 ⁵⁰
TO TRANSFER REAR DOOR MECHANISM				100.00 ⁵⁰
TO TRANSFER TYRE TO NEW RIM AND BALANCING				50.00 ³⁰
TO VACUUM, RE-OIL AND RE-GAS AIR CON				120.00 ¹⁰⁰
TO REMOVE/REFIX TRIM BOARD, CARPETS, GARNISHES TO FACILITATE REPAIRS				280.00 ¹²⁰
TO REMOVE/REPLACE UNDERCARRIAGE PARTS				400.00 ^{280?}
TO CUT OUT/RE-WELD RH REAR FENDER, RH FRONT DOOR PILLAR REPAIR RH WINDSCREEN PILLAR, RH ROCKER PANEL, CENTRE PANEL INCLUDING REPLACEMENT OF PARTS				1,800.00 ¹⁵⁰⁰
TO SPRAY PAINT RH FRONT FENDER, RH FRONT DOOR PILLAR, RH FRONT DOOR, RH SLIDING DOOR, RH REAR FENDER, RH ROCKER PANEL, RH CENTRE PANEL, RH WINDSCREEN PILLAR				2,000.00 ¹⁵⁰⁰
Labour Total S\$:				5,120.00
E. & O.E.			Total S\$:	21,247.00

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
 Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
 Website: www.falconair.com.sg Email: email@falconair.com.sg

Taufan 97495749
 Ex - \$3000 26/10/22
 Not Antwaise 0330pm
 L/S resurvey before paint
 Taufan @ Khantown
 10 days
 To check repair limit