

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

ZAIDI BIN UTTU
BLK 863 WOODLANDS ST 83 #02-190
SINGAPORE 730863

Contact : 96719287, 94288886

TAX INVOICE

Repair Code : CLM15698

Date in : 25/10/2022

Vehicle Num. : SGW9829M

Model : MITSUBISHI LANCER EX 1.6 AT LED TAIL LAMP

Chassis/Eng# : JMYSRCY1AGU006869/4A92CP5276

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BONNET	1	809.00	+ 809.00
FRONT BONNET HINGES L/R	2	55.00	+ 110.00
FRONT BONNET MECHANISM LOCK	1	50.00	+ 50.00
FRONT BUMPER	1	858.00	✓ 858.00
FRONT BUMPER FOGLAMP GARNISH RH	1	85.00	✓ 85.00
FRONT BUMPER FOGLAMP RH	1	426.00	✓ 426.00
FRONT BUMPER LED LAMP RH	1	586.00	✓ 586.00
FRONT BUMPER LOWER GRILLE	1	168.00	✓ 168.00
FRONT BUMPER LOWER GRILLE COVER L/R	2	12.00	+ 24.00
FRONT BUMPER LOWER GRILLE OUTER CHROME MOULDING	1	221.00	✓ 221.00
FRONT BUMPER REINFORCEMENT	1	390.00	✓ 390.00
FRONT BUMPER RH ANS STANLEY MODULE	1	502.10	✓ 502.10
FRONT BUMPER RIVET	10	6.00	✓ 60.00
FRONT BUMPER SIDE BRACKET L/R	2	16.00	+ 32.00
FRONT BUMPER SIDE RETAINER L/R	2	18.00	18- 36.00
FRONT BUMPER TOP BRACKET	1	167.00	X 167.00
FRONT BUMPER UNDER COVER	1	156.00	+ 156.00
FRONT FENDER INNER SHIELD RH	1	102.00	✓ 102.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

ZAIDI BIN UTTU
 BLK 863 WOODLANDS ST 83 #02-190
 SINGAPORE 730863

Contact : 96719287, 94288886

TAX INVOICE

Repair Code : CLM15698

Date in : 25/10/2022

Vehicle Num. : SGW9829M

Model : MITSUBISHI LANCER EX 1.6 AT LED TAIL LAMP

Chassis/Eng# : JMYSRCY1AGU006869/4A92CP5276

FRONT FENDER RH	<i>Buch d.</i>	1	588.00	✓	588.00
FRONT GRILLE	<i>Ambed.</i>	1	254.00	✓	254.00
FRONT GRILLE EMBLEM	<i>me</i>	1	48.00	✓	48.00
FRONT HEADLAMP CLIPS L/R	<i>me</i>	2	6.00	6	12.00
FRONT HEADLAMP L/R	<i>RTA crambd</i>	2	698.00	688	1,396.00
FRONT HEADLAMP TOP PANEL L/R	<i>me</i>	2	78.00	X	156.00
FRONT SUPPORT PANEL TOP GARNISH	<i>me</i>	1	63.00	+	63.00
FRONT SUPPORT SIDE PANEL RH	<i>me</i>	1	155.00	+	155.00
FRONT SUPPORT TOP PANEL	<i>me</i>	1	267.00	+	267.00
FRONT WASHER TANK	<i>Delnd</i>	1	85.00	✓	85.00
FRONT WASHER TANK MOTOR	<i>me</i>	1	139.00	+	139.00

Subtotal before discount

7,945.10

Percentage discount 10%

794.51

Sub-total 1

7,150.59

FRONT BONNET INSULATOR CLIPS - SET	<i>me</i>	1	50.00	+	50.00
FRONT BUMPER CLIPS - SET	<i>me</i>	1	50.00	30	50.00
FRONT BUMPER NUMBER PLATE	<i>2 10p</i>	1	25.00	+	25.00
FRONT BUMPER NUMBER PLATE HOLDER	<i>me</i>	1	50.00	+	50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

ZAIDI BIN UTTU
BLK 863 WOODLANDS ST 83 #02-190
SINGAPORE 730863

Contact : 96719287, 94288886

TAX INVOICE

Repair Code : CLM15698

Date in : 25/10/2022

Vehicle Num. : SGW9829M

Model : MITSUBISHI LANCER EX 1.6 AT LED TAIL LAMP

Chassis/Eng# : JMYSRCY1AGU006869/4A92CP5276

FRONT FENDER INNER SHIELD CLIPS RH - SET	1	50.00	50.00
FRONT SUPPORT PANEL TOP GARNISH CLIPS - SET	1	50.00	50.00
Subtotal before discount			275.00
Percentage discount	0%		0.00
Sub-total 2			275.00
Parts-total			7,425.59

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

2,260.00

9,685.59

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5575.59
L/S: A7K ✓