



Auto 101 LLP

No. 2 Yishun Industrial St 1
Northpoint Bizhub, #02-01
Singapore 768159
Tel: 67545101
DATE: 26-10-2022

REPAIR ESTIMATE

VEHICLE: SGF 2840 P
MODEL: Toyota Altis

S/n	Description of part	Qty	Estimate
1	Front Door RH <i>X Repair</i>	1	
2	Front door chrome protector RH <i>— Cut</i>	1	
3	Rear Door RH <i>X Repair</i>	1	
4	Rear Door chrome protector RH <i>— Cut</i>	1	
5	Rear bumper <i>X Repair</i>	1	
6	Rear bumper Side retainer RH <i>X ?</i>	1	
7	Rear bumper clip - set <i>X ?</i>	1	
Sub-total 1			
Less 25%			
8	Rear sports rim RH <i>X Repair</i>	1	
Sub-total 2			
Parts total			

Labour			
9	To straighten and panel side panel, remove and replace part.	800.00	<i>400</i>
10	To putty, re-spray painting and polish front affected areas.	1,000.00	<i>800</i>
11	To remove and transfer door component	150.00	<i>X 60</i>
12	To conduct <i>wheel</i> electronic alignment	120.00	<i>X 60</i>
13	To rust proof affected areas	60.00	<i>X</i>
14	To check and rectify wiring	60.00	<i>X</i>
Labour total		2,190.00	
Part and Labour total			

4 Days.

Unsprung repair

After repair photos.

Eric Qi ang

82880282

27/10/22.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damage sheet for insurance resurvey
- Parts price to be agreed on "no dispute" basis
- Third party survey to be conducted on "no dispute" basis
- No ill will, if not satisfied, please return to the insurance company
- Supplier to be approved and is subject to the insurance company

Acknowledged by Repairer:

Signature:

Date: