



Case Details

Case Reference Number : TAX/10/22/2071
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1773R

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-19673-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AXA Insurance Singapore Pte Ltd
 Accident Date and Time : 23/10/2022 06:41 AM
 Vehicle Age(In Months) : 11

Documents / Photographs

[View Documents / Photographs](#)

Total Documents : 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation					Surveyor Approval					Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			DOOR ASM-FRT SI - RH	1	2,338.44	2,338.44	30.00	1,636.91	Replace	1	0	Repair	X R
Standard	Main			STICKER STRIDES TAXI (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	/ nec
Standard	Main			DOOR ASM-RR SI - RH	1	2,185.04	2,185.04	30.00	1,529.53	Replace	1	1,529.53	Replace	/ DD
Standard	Main			HINGE ASM-RR S/D UPR-RH	1	46.90	46.90	30.00	32.83	Replace	0	0	Not Give	X nn
Standard	Main			CHECK ASM-RR S/D -RH	1	21.00	21.00	30.00	14.70	Replace	0	0	Not Give	X nn
Standard	Main			HINGE ASM-RR S/D LWR-RH	1	47.22	47.22	30.00	33.05	Replace	0	0	Not Give	X nn
Standard	Main			REGULATOR ASM-RR S/D WDO-RH	1	265.30	265.30	10.00	238.77	Replace	0	0	Check	? X nn
Standard	Main			LATCH ASM-RR S/D -RH	1	139.98	139.98	10.00	125.98	Replace	0	0	Not Give	X nn
Standard	Main			PANEL-BODY SI OTR - RH	1	1,434.89	1,434.89	30.00	1,004.42	Replace	1	0	Repair	X R
Standard	Main			STICKER ELECTRIC (LOGO	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	/ nec
Standard	Main			LINER ASM-RR W/H PNL -RH	1	85.48	85.48	30.00	59.84	Replace	0	0	Not Give	X nn
Standard	Main			FASCIA-RR BPR	1	758.48	758.48	30.00	530.94	Replace	1	0	Repair	X R
Standard	Main			FASCIA-RR BPR LWR	1	230.68	230.68	30.00	161.48	Replace	0	0	Not Give	X nn
Standard	Main			BRACKET-RR BPR FASCIA SI MTG - RH	1	46.08	46.08	30.00	32.26	Replace	0	0	Check	? X nn
Standard	Main			WHEEL	1	618.07	618.07	30.00	432.65	Replace	1	0	Repair	X R

Total Spare Part Cost 7,558.13

Surveyor Total 1,618.05

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 7,558.13

Final Sur Total 1,618.05

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			BEARING ASM-RR WHL	1	335.40	335.40	30.00	234.78	Replace	0	0	Not Give	✓ X nn
Standard	Main			BEAM ASM-RR SUSP EQLZR	1	1,649.54	1,649.54	30.00	1,154.68	Replace	0	0	Not Give	✓ X nn
One Time Key In	Main			FILM-RR S/D FRM - RH	1	9.88	9.88	30.00	6.92	Replace	1	6.92	✓ Replace	✓ / nec
One Time Key In	Main			MOLDING ASM-RR S/D WDO UPR RVL - RH	1	54.50	54.50	30.00	38.15	Replace	0	0	Not Give	✓ X nn
One Time Key In	Main			FILM-RR S/D FRM - RH	1	9.88	9.88	30.00	6.92	Replace	0	0	Not Give	✓ X nn
One Time Key In	Main			WEATHERSTRIP ASM-RR S/D (BODY SI) - RH	1	74.46	74.46	30.00	52.12	Replace	0	0	Not Give	✓ X nn
One Time Key In	Main			WEATHERSTRIP ASM-RR S/D (DR SI) - RH	1	71.76	71.76	30.00	50.23	Replace	0	0	Not Give	✓ X nn
One Time Key In	Main			WEATHERSTRIP ASM-RR S/D WDO INR - RH	1	27.98	27.98	30.00	19.59	Replace	0	0	Not Give	✓ X nn
One Time Key In	Main			WEATHERSTRIP ASM-RR S/D WDO OTR - RH	1	69.26	69.26	30.00	48.48	Replace	0	0	Not Give	✓ X nn
One Time Key In	Main			BAR-RR S/D WDO DIV - RH	1	44.72	44.72	30.00	31.30	Replace	0	0	Check	✓ ? X nn

Total Spare Part Cost 7,558.13

Surveyor Total 1,618.05

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 7,558.13

Final Sur Total 1,618.05

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	2,400.00	400.00	
Total:			2,400.00	400.00	✓

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY RIM	230.00	150	
2	Main	TO RESPRAY FRONT DOOR RH	428.00	220	
3	Main	TO RESPRAY ROCKER PANEL MOULDING	230.00	150	
4	Main	TO RESPRAY RH REAR DOOR	428.00	220	
5	Main	TO RESPRAY REAR FENDER RH	428.00	220	
Total:			2,172.00	1,180.00	✓

Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
6 Main	TO RESPRAY REAR BUMPER	428.00	220	
Total:		2,172.00	1,180.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	/ nec
2	Main	TO WASH AND VACUUM	60.00	0	X nn
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0	X nn
4	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	/ nec
5	Main	TO TRANSFER DOOR MECHANISM	120.00	30	/ nec
6	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	X nn
7	Main	TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0	X nn
8	Main	TO REPLACE SUNDRY PARTS	100.00	20	/ nec
9	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	150	/ nec
10	Main	ISOLATED OF (EV) (NET)	150.00	150.00	/ nec
Total:			1,360.00	430.00	✓

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	7,558.13	1,618.05
Total Labour Cost	2,400.00	400.00
Total Spray Painting	2,172.00	1,180.00
Other	1,360.00	430.00
Overall Total	13,490.13	3,628.05
Lump Sum Repair Option		
Lump Sum Total	0.00	3,628.05
Surveyor Approved Amount		3,628.05
No of Repair Days*	8	4

Estimator Assessment(\$)

Surveyor Assessment(\$)

Remarks

PART BY PART / BEFORE PAINT PHOTO FOR CHECK ITEM
AND REPLACE ITEM PLEASE CALL SURVEYOR Steve
Chen (LKK) / UR : 9272 0012 & Email: stevenchen@lkk.com

Surveyor Name

STEVE CHEN

Signature



Save

Clear

Survey Date

25/10/2022

Steve (LKK)
25/10/22, 5-30pm
with Prejudice
14 days
P/P
Resury Before Spray

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: