

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0916/2022/EQ
DATE : 21-Oct-22
WIP : 46935

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 25/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

7 days exclude 1 S

Johnny Boo 13 Feb

OWNER'S NAME : MS CHAN PEK SIAN DIANA
ADDRESS : 13 FERNVALE CLOSE
#18-14
SINGAPORE 797476
TELEPHONE : HP +65 90233999
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210114464
VEHICLE NO : **SJU 9895 X**
MODEL CODE : AUDI Q3 SPORTBACK 1.4 TFS
MODEL YEAR : 29/9/2021
ENGINE NO : CZD C48856
CHASSIS NO : WAUZZZF37M1153300
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Oct-22
PLACE OF ACCIDENT : CONDO BASEMENT CARPARK AT
B.FERNVALE CLOSE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJU 9395 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00 \$	360.00
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY.	S/N \$	480.00 \$	480.00
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$	480.00 \$	480.00
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00 \$	400.00
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00 \$	150.00
TOTAL LABOUR CHARGES		: \$	1,920.00 \$	1,870.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJU 9895 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 1,870.00
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR RHS TAILLAMP PANEL AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	3,200.00	\$ 1,000.00
7	TO RESPRAY REAR BUMPER, REAR LID, RHS TAILLAMP PANEL, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS.	\$	4,500.00	\$ 2,050.00
8	SUPPLEMENTARY	\$	4,000.00	\$ 3,100.00
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 13,812.00	\$ 8,212.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJU 9895 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1 \$	1,738.00 \$	1,390.40
2	REAR BUMPER SPOILER	1 \$	510.00 \$	408.00
3	REAR BUMPER GRILLE - RH	1 \$	170.00 \$	135.60
4	REAR PARKING AID SENSOR SUPPORT - RH	1 \$	28.00 \$	22.08
5	REAR BUMPER ADAPTER - RH	1 \$	95.00	
6	REAR BUMPER BRACKET	1 \$	53.00	
7	REAR BUMPER REFLECTOR - RH	1 \$	46.00 \$	36.48
8	REAR OUTER TAIL LIGHT - RH	1 \$	1,030.00 \$	824.00
9	REAR OUTER TAIL LIGHT TRIM - RH	1 \$	34.00 \$	26.48
10	REAR INNER TAIL LIGHT - RH	1 \$	1,030.00 \$	824.00
11	REAR INNER TAIL LIGHT TRIM - RH	1 \$	34.00 \$	26.48
12	REAR BUMPER REINFORCEMENT BEAM	1 \$	693.00	
13	REAR BUMPER SHOCK ABSORBER	1 \$	95.00	
14	REAR BUMPER HOLDING STRAP - LH / RH	2 \$	64.00	
15	REAR BUMPER GUIDE SECTION - RH	1 \$	71.00	
16	REAR PARKING AID SENSOR - INNER / OUTER	2 \$	531.00	
17	REAR PARKING AID SEAL RING	4 \$	10.00	
18	REAR BUMPER WIRING SET	1 \$	449.00 \$	358.80
19	REAR UNDERBODY TRIM - RH	1 \$	58.00	
20	REAR LID	1 \$	3,728.00 \$	2,982.40
SUB TOTAL SPARE PARTS		:	\$ 10,467.00 \$	7,034.72

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJU 9895 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 7,034.72
21	PACKING ADHESIVE	1 \$	21.00 \$	16.80
22	REAR LID FLAP GASKET	1 \$	229.00	
23	REAR LID STOP BUFFER - LH / RH	2 \$	61.00	
24	AUDI EMBLEM	1 \$	144.00 \$	114.80
25	"Q3" INSCRIPTION	1 \$	104.00 \$	82.80
26	REAR WINDSCREEN	1 \$	1,064.00 \$	851.20
27	WINDSCREEN PRIMER	1 \$	22.00 \$	17.36
28	REAR SPOILER - LH / RH	2 \$	470.00 \$	375.20
29	REAR VENT TRIM	1 \$	79.00	
30	REAR WHEEL COVER - LH / RH	2 \$	1,132.00 \$	904.80
31	REAR WINDSCREEN SEALANT	S/N \$	200.00 \$	200.00
32	ADD PARTS	\$	1,358.00 \$	1,241.52
33	SUNDRIES	\$	500.00 \$	48.48
TOTAL SPARE PARTS		:	\$ 15,851.00	\$ 10,887.68
TOTAL LABOUR CHARGES		:	\$ 13,812.00	\$ 8,212.00
GRAND TOTAL		:	\$ 29,663.00	\$ 19,099.68

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-29/12/22



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0916/2022/EQ 12-Dec-22 CHANG 1 of 1 SJU 9895 X AUDI Q3 SPORTBACK 1.4 TFSI	
Quantity	Description		Unit Price	Amount
<u>Labours</u>				
1	TO DISLODGE AND REINSTALL REAR WIRE S/N HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.		\$ 1,600.00	\$ 1,600.00
2	TO CUT OUT AND WELD REAR END OUTER PANEL. TO REPAIR REAR END INNER PANEL AND REAR FENDER CONNECTING PLATE.		\$ 2,400.00	\$ 1,500.00
			\$ 4,000.00	\$ 3,100.00
<u>Parts</u>				
1	REAR END PANEL - OUTER	1	\$ 445.00	\$ 355.60
2	REAR LID BUNG	4	\$ 133.00	\$ 105.92
3	ACRYLIC SEALER	S/N	\$ 180.00	\$ 180.00
4	CAVITY WAX	S/N	\$ 140.00	\$ 140.00
5	STONE CHIP	S/N	\$ 180.00	\$ 180.00
6	METAL FILLER POWDER	S/N	\$ 280.00	\$ 280.00
MATERIALS			\$ 1,358.00	\$ 1,241.52
LABOUR			\$ 4,000.00	\$ 3,100.00
GRAND TOTAL			\$ 5,358.00	\$ 4,341.52

For Premium Automobiles Pte Ltd

Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LABOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT