

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0916/2022/EQ
DATE : 21-Oct-22
WIP : 46935

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 25/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS CHAN PEK SIAN DIANA
ADDRESS : 13 FERNVALE CLOSE
#18-14
SINGAPORE 797476
TELEPHONE : HP +65 90233999
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210114464
VEHICLE NO : **SJU 9895 X**
MODEL CODE : AUDI Q3 SPORTBACK 1.4 TFS
MODEL YEAR : 29/9/2021
ENGINE NO : CZD C48856
CHASSIS NO : WAUZZZF37M1153300
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Oct-22
PLACE OF ACCIDENT : CONDO BASEMENT CARPARK AT
B.FERNVALE CLOSE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJU 9895 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY.	S/N \$	480.00	✓
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$	480.00	✓
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	✓
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	150 ✓
TOTAL LABOUR CHARGES		:	\$ 1,920.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJU 9895 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR RHS TAILLAMP PANEL AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00 888. 7050	1000 ✓ 550x2 = 1100
7	TO RESPRAY REAR BUMPER, REAR LID, RHS TAILLAMP PANEL, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS.	\$ 4,500.00 1500	wheel dic x2 = 400
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 9,812.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJU 9895 X
DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Delcd</i>	1 \$	1,738.00 ✓	1390.40
2	REAR BUMPER SPOILER <i>Delcd</i>	1 \$	510.00 ✓	408
3	REAR BUMPER GRILLE - RH <i>Delcd</i>	1 \$	170.00 ✓	135.60
4	REAR PARKING AID SENSOR SUPPORT - RH <i>Thy d</i>	1 \$	28.00 ?	22.08 ✓
5	REAR BUMPER ADAPTER - RH <i>NE new</i>	1 \$	95.00 ? X	
6	REAR BUMPER BRACKET <i>NE new</i>	1 \$	53.00 ? X	
7	REAR BUMPER REFLECTOR - RH <i>Cracked</i>	1 \$	46.00 ✓	36.48
8	REAR OUTER TAIL LIGHT - RH <i>Cracked</i>	1 \$	1,030.00 ✓	874
9	REAR OUTER TAIL LIGHT TRIM - RH <i>* ? Cracked</i>	1 \$	34.00 ✓	26.48
10	REAR INNER TAIL LIGHT - RH <i>Cracked</i>	1 \$	1,030.00 ✓	874
11	REAR INNER TAIL LIGHT TRIM - RH <i>Missing</i>	1 \$	34.00 ✓	26.48
12	REAR BUMPER REINFORCEMENT BEAM <i>new</i>	1 \$	693.00 +	
13	REAR BUMPER SHOCK ABSORBER <i>NE new</i>	1 \$	95.00 ? X	
14	REAR BUMPER HOLDING STRAP - LH / RH <i>NE new</i>	2 \$	64.00 ? X	
15	REAR BUMPER GUIDE SECTION - RH <i>NE new</i>	1 \$	71.00 ? X	
16	REAR PARKING AID SENSOR - INNER / OUTER <i>new</i>	2 \$	531.00 +	
17	REAR PARKING AID SEAL RING <i>new</i>	4 \$	10.00 X	
18	REAR BUMPER WIRING SET <i>new cut</i>	1 \$	449.00 ✓	358.80
19	REAR UNDERBODY TRIM - RH <i>new</i>	1 \$	58.00 +	
20	REAR LID <i>Dented</i>	1 \$	3,728.00 ✓	2982.40
SUB TOTAL SPARE PARTS		:	\$ 10,467.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJU 9895 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	PACKING ADHESIVE <i>new</i>	1 \$	21.00	✓ 16.80
22	REAR LID FLAP GASKET <i>new</i>	1 \$	229.00	+
23	REAR LID STOP BUFFER - LH / RH <i>new</i>	2 \$	61.00	+
24	AUDI EMBLEM <i>new</i>	1 \$	144.00	✓ 114.80
25	"Q3" INSCRIPTION <i>new</i>	1 \$	104.00	✓ 82.80
26	REAR WINDSCREEN <i>new</i>	1 \$	1,064.00	✓ 851.20
27	WINDSCREEN PRIMER <i>new</i>	1 \$	22.00	✓ 17.36
28	REAR SPOILER - LH / RH <i>new</i>	2 \$	470.00	✓ 375.20
29	REAR VENT TRIM <i>new</i>	1 \$	79.00	+
30	REAR WHEEL COVER - LH / RH <i>new</i>	2 \$	1,132.00	✓ 904.80
31	REAR WINDSCREEN SEALANT <i>new</i>	S/N \$	200.00	✓
32	SUNDRIES <i>new</i>	\$	500.00	? 48.48 ✓
TOTAL SPARE PARTS		:	\$	14,493.00
TOTAL LABOUR CHARGES		:	\$	9,812.00
GRAND TOTAL		:	\$	24,305.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Xiao Chen

Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0916/2022/EQ

12-Dec-22

CHANG



1 of 1

SJU 9895 X

AUDI Q3 SPORTBACK 1.4 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY. S/N	\$ 1,600.00	✓
2	TO CUT OUT AND WELD REAR END OUTER PANEL. TO REPAIR REAR END INNER PANEL AND REAR FENDER CONNECTING PLATE.	\$ 2,400.00	1500. ✓
Parts			
1	REAR END PANEL - OUTER <i>Dented</i>	\$ 445.00	✓ <i>355.60</i>
2	REAR LID BUNG <i>New</i>	\$ 133.00	✓ <i>105.92</i>
3	ACRYLIC SEALER <i>2 per</i>	\$ 180.00	✓
4	CAVITY WAX	\$ 140.00	✓
5	STONE CHIP	\$ 180.00	✓
6	METAL FILLER POWDER <i>per</i>	\$ 280.00	✓
GRAND TOTAL			\$ 5,358.00

For Premium Automobiles Pte Ltd

Authorised Signature

Adrian Ling
Stef. Penneyed.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lij*
SURVEYED DATE : *25/10/22*
AUTHORISED DATE : *fls*
EXCESS COST : *07 Days*
LIABILITY : *08 Days*
REMARKS : *Not Authorised*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT