

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0915/2022/EQ
DATE : 21-Oct-22
WIP : 47068

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 25/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian
8 days exclude 1 Sunday
Johnny Boo 13 Feb 23

OWNER'S NAME : MR TAN HEA HONG
ADDRESS : 1A CANTONMENT ROAD
#34-03
SINGAPORE 085101
TELEPHONE : HP +65 97628069
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100461226-06
VEHICLE NO : **SGX 9449 X**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR : 25/4/2016
ENGINE NO : CVN 006845
CHASSIS NO : WAUZZZF40GA049082
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Oct-22
PLACE OF ACCIDENT : HOTEL FORT CANNING CAR PARK EXIT

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGX 9449 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	\$	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	1,400.00	\$	1,400.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,900.00	\$	2,750.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET.	\$	3,000.00	\$	1,650.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 10,202.00	\$	6,602.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGX 9449 X

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,377.00	\$	1,901.60
2	FRONT BUMPER FIXING PARTS	1	\$ 612.00		
3	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 79.00		
4	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00	\$	174.80
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 254.00	\$	203.20
6	FRONT BUMPER AIR GUIDE - RH	1	\$ 72.00		
7	RADIATOR GRILLE	1	\$ 2,019.00	\$	1,615.20
8	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 409.00	\$	326.80
9	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00		
10	FRONT BUMPER FOAM FILLER PIECE	1	\$ 139.00	\$	110.80
11	FRONT BUMPER GUIDE SECTION - RH	1	\$ 41.00	\$	32.24
12	FRONT BUMPER BRACKET - RH	1	\$ 254.00		
13	FRONT BUMPER TOP COVER	1	\$ 143.00	\$	114.00
14	CAUTION SIGN STICKER	1	\$ 16.00	\$	12.40
15	AIR CONDITIONER STICKER	1	\$ 9.00	\$	6.64
16	FRONT BUMPER BRACKET - RH	1	\$ 154.00	\$	122.80
17	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00		
18	HORN LOW TONE - RH	1	\$ 139.00		
19	HORN BRACKET - RH	1	\$ 33.00		
20	FRONT FENDER - RH	1	\$ 861.00	\$	688.80
SUB TOTAL SPARE PARTS		:	\$ 8,793.00	\$	5,309.28

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGX 9449 X

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
		<i>c/f</i>		\$	<i>5,309.28</i>
21	FRONT FENDER ATTACHMENT PARTS	1	\$	225.00	
22	FRONT FENDER CLOSING ELEMENT - RH	1	\$	81.00	<i>\$ 64.24</i>
23	FRONT FENDER BRACKET - RH	1	\$	41.00	<i>\$ 32.72</i>
24	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	1	\$	55.00	
25	FRONT FENDER RIVET	7	\$	27.00	<i>\$ 21.28</i>
26	FRONT FENDER BRACE - RH	1	\$	132.00	<i>\$ 105.20</i>
27	FRONT WHEEL HOUSING LINER - RH	1	\$	262.00	<i>\$ 209.60</i>
28	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$	149.00	
29	FRONT WHEEL SPOILER - RH	1	\$	82.00	<i>\$ 65.60</i>
30	FRONT WHEEL SPOILER END PLATE - RH	1	\$	40.00	<i>\$ 32.00</i>
31	FRONT STONE CHIP GUARD - RH	1	\$	57.00	
32	FRONT FENDER LEDGE COVER - RH OUTER	1	\$	35.00	<i>\$ 27.52</i>
33	FRONT FENDER LEDGE COVER - RH	1	\$	26.00	<i>\$ 20.16</i>
34	BONNET	1	\$	3,425.00	<i>\$ 2,740.00</i>
35	BONNET ATTACHMENT PARTS	1	\$	431.00	
36	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$	93.00	<i>\$ 73.20</i>
37	BONNET STRIKER	1	\$	56.00	
38	BONNET LOCK	1	\$	228.00	
39	BONNET BOWDEN CABLE	1	\$	64.00	
40	BONNET RELEASE LEVER	1	\$	15.00	
SUB TOTAL SPARE PARTS		:	\$	5,524.00	<i>\$ 8,700.80</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGX 9449 X

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	8,700.80
41	HEADLIGHT - RH	1	\$ 8,294.00	\$	6,635.20
42	HEADLIGHT POWER MODULE	1	\$ 842.00		
43	HEADLIGHT CONTROL UNIT	1	\$ 840.00	\$	672.00
44	HEADLIGHT HOSE	1	\$ 42.00		
45	HEADLIGHT COMPENSATING PIECE	1	\$ 45.00		
46	HEADLIGHT COMPENSATING PIECE	1	\$ 47.00		
47	HEADLIGHT COMPENSATING PIECE	1	\$ 45.00		
48	LIFT CYLINDER - RH	1	\$ 231.00	\$	184.40
49	LIFT CYLINDER BRACKET	1	\$ 7.00	\$	5.44
50	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00		
51	LIFT CYLINDER CORRUGATED PIPE	1	\$ 45.00		
52	LOCK CARRIER	1	\$ 1,478.00	\$	901.60
53	RADIATOR SUPPORT BRACKET	1	\$ 43.00		
54	RADIATOR - LOWER CENTRE	1	\$ 545.00		
55	RADIATOR COOLANT	1	\$ 699.00		
56	A/C CONDENSER	1	\$ 683.00		
57	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00		
58	READY-MIX COOLANT	6	\$ 297.00	\$	237.12
59	RADIATOR AIR GUIDE - RH INNER	1	\$ 32.00		
60	RADIATOR AIR GUIDE - LH / RH OUTER	2	\$ 28.00		
SUB TOTAL SPARE PARTS		:	\$ 14,371.00	\$	17,336.56

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGX 9449 X

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>17,336.56</i>
61	RADIATOR AIR GUIDE - UPPER CENTER	1	\$ 19.00		
62	RADIATOR AIR GUIDE - LOWER	1	\$ 25.00		
63	INTAKE AIR DUCT - RH LOWER	1	\$ 25.00		
64	INTAKE AIR DUCT - CENTER	1	\$ 61.00		
65	INTAKE HOSE	1	\$ 110.00		
66	AIR FILTER	1	\$ 418.00		
67	NOISE INSULATION	1	\$ 640.00	<i>\$</i>	<i>512.00</i>
68	FRONT NO PLATE	S/N	\$ 60.00	<i>\$</i>	<i>60.00</i>
69	SUNDRIES		\$ 500.00	<i>\$</i>	<i>3.04</i>
TOTAL SPARE PARTS		:	\$ 30,546.00	<i>\$</i>	<i>17,911.60</i>
TOTAL LABOUR CHARGES		:	\$ 10,202.00	<i>\$</i>	<i>6,602.00</i>
GRAND TOTAL		:	\$ 40,748.00	<i>\$</i>	<i>24,513.60</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-15/12/22



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT