

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Xiacon.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGX 9449 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00 ✓	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 250	
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00 ✓ <i>H/S.</i>	
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00 1500 + 1250. <i>H/S.</i>	
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET.	\$ 3,000.00 1650	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		\$ 10,202.00	

+ 3 days

Adrian Lj
Remixed
H/S.

Add 3 days for replacement of lock carrier

ACar-in

23/10/22

PREMIUM AUTOMOBILES

WP=47068



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGX 9449 X

Bent after Accident - 5 days

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER Distorted.	1 \$	2,377.00	✓
2	FRONT BUMPER FIXING PARTS New	1 \$	612.00	+
3	FRONT BUMPER SECURING STRIP - LH / RH ?	2 \$	79.00	?
4	FRONT BUMPER GRILLE - CENTER New	1 \$	219.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE replaced.	1 \$	254.00	✓ H/S
6	FRONT BUMPER AIR GUIDE - RH Distorted?	1 \$	72.00	✓ ?
7	RADIATOR GRILLE Int	1 \$	2,019.00	✓
8	FRONT BUMPER AIR GUIDE GRILLE - RH Distorted	1 \$	409.00	✓
9	FRONT BUMPER REINFORCEMENT BEAM ?	1 \$	899.00	?
10	FRONT BUMPER FOAM FILLER PIECE Behind	1 \$	139.00	✓ H/S
11	FRONT BUMPER GUIDE SECTION - RH Distorted	1 \$	41.00	✓
12	FRONT BUMPER BRACKET - RH ?	1 \$	254.00	?
13	FRONT BUMPER TOP COVER Int	1 \$	143.00	✓ H/S
14	CAUTION SIGN STICKER Green	1 \$	16.00	✓ H/S
15	AIR CONDITIONER STICKER	1 \$	9.00	✓
16	FRONT BUMPER BRACKET - RH Int	1 \$	154.00	✓ H/S
17	FRONT BUMPER SUPPORT - LH / RH ?	2 \$	64.00	?
18	HORN LOW TONE - RH Green	1 \$	139.00	+
19	HORN BRACKET - RH	1 \$	33.00	+
20	FRONT FENDER - RH Distorted	1 \$	861.00	✓
SUB TOTAL SPARE PARTS			\$ 8,793.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGX 9449 X

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER ATTACHMENT PARTS <i>Neu</i>	1	\$ 225.00	<i>x</i>
22	FRONT FENDER CLOSING ELEMENT - RH <i>2nd</i>	1	\$ 81.00	<i>3 l/s</i>
23	FRONT FENDER BRACKET - RH <i>Best</i>	1	\$ 41.00	<i>3 l/s</i>
24	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH ?	1	\$ 55.00	<i>?</i>
25	FRONT FENDER RIVET <i>neu</i>	7	\$ 27.00	<i>3 l/s</i>
26	FRONT FENDER BRACE - RH <i>Best</i>	1	\$ 132.00	<i>3 l/s</i>
27	FRONT WHEEL HOUSING LINER - RH <i>neu Delid</i>	1	\$ 262.00	<i>3 l/s</i>
28	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>neu</i>	1	\$ 149.00	<i>+</i>
29	FRONT WHEEL SPOILER - RH <i>neu ton</i>	1	\$ 82.00	<i>3 l/s</i>
30	FRONT WHEEL SPOILER END PLATE - RH <i>neu 2nd</i>	1	\$ 40.00	<i>x</i>
31	FRONT STONE CHIP GUARD - RH <i>neu</i>	1	\$ 57.00	<i>+</i>
32	FRONT FENDER LEDGE COVER - RH OUTER <i>neu</i>	1	\$ 35.00	<i>3 l/s</i>
33	FRONT FENDER LEDGE COVER - RH <i>2nd</i>	1	\$ 26.00	<i>3 l/s</i>
34	BONNET <i>Delid</i>	1	\$ 3,425.00	<i>✓</i>
35	BONNET ATTACHMENT PARTS <i>neu</i>	1	\$ 431.00	<i>x</i>
36	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>neu</i>	3	\$ 93.00	<i>✓</i>
37	BONNET STRIKER <i>neu</i>	1	\$ 56.00	<i>+</i>
38	BONNET LOCK <i>neu</i>	1	\$ 228.00	<i>x</i>
39	BONNET BOWDEN CABLE <i>neu</i>	1	\$ 64.00	<i>+</i>
40	BONNET RELEASE LEVER <i>neu</i>	1	\$ 15.00	<i>+</i>
SUB TOTAL SPARE PARTS			\$ 5,524.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGX 9449 X

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	HEADLIGHT - RH <i>cut</i>	1	\$ 8,294.00	✓	
42	HEADLIGHT POWER MODULE <i>new</i>	1	\$ 842.00	✗	
43	HEADLIGHT CONTROL UNIT <i>Dented</i>	1	\$ 840.00	✓	<i>h/s</i>
44	HEADLIGHT HOSE <i>Not in</i>	1	\$ 42.00	✗	
45	HEADLIGHT COMPENSATING PIECE	1	\$ 45.00	✗	
46	HEADLIGHT COMPENSATING PIECE	1	\$ 47.00	✗	
47	HEADLIGHT COMPENSATING PIECE	1	\$ 45.00	✗	
48	LIFT CYLINDER - RH <i>new could</i>	1	\$ 231.00	✗	<i>h/s</i>
49	LIFT CYLINDER BRACKET <i>Not in Dented</i>	1	\$ 7.00	✗	<i>h/s</i>
50	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00	✗	
51	LIFT CYLINDER CORRUGATED PIPE	1	\$ 45.00	✗	
52	LOCK CARRIER <i>Not in could</i>	1	\$ 1,478.00	✗	<i>h/s</i>
53	RADIATOR SUPPORT BRACKET	1	\$ 43.00	✗	
54	RADIATOR - LOWER CENTRE	1	\$ 545.00	✗	
55	RADIATOR COOLANT <i>new</i>	1	\$ 699.00	✗	
56	A/C CONDENSER <i>Not in</i>	1	\$ 683.00	✗	
57	OUTSIDE TEMPERATURE SENSOR BRACKET <i>new</i>	1	\$ 21.00	✗	
58	READY-MIX COOLANT <i>new</i>	6	\$ 297.00	✓	<i>h/s</i>
59	RADIATOR AIR GUIDE - RH INNER <i>new</i>	1	\$ 32.00	✗	
60	RADIATOR AIR GUIDE - LH / RH OUTER	2	\$ 28.00	✗	
SUB TOTAL SPARE PARTS		:	\$ 14,371.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGX 9449 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
61	RADIATOR AIR GUIDE - UPPER CENTER	1	\$	19.00	X
62	RADIATOR AIR GUIDE - LOWER	1	\$	25.00	X
63	INTAKE AIR DUCT - RH LOWER	1	\$	25.00	X
64	INTAKE AIR DUCT - CENTER	1	\$	61.00	X
65	INTAKE HOSE	1	\$	110.00	X
66	AIR FILTER	1	\$	418.00	X
67	NOISE INSULATION	1	\$	640.00	X
68	FRONT NO PLATE	S/N	\$	60.00	X
69	SUNDRIES		\$	500.00	X
TOTAL SPARE PARTS		:	\$	30,546.00	
TOTAL LABOUR CHARGES		:	\$	10,202.00	
GRAND TOTAL		:	\$	40,748.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.