

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0926/2022/EQ
DATE : 25-Oct-22
WIP : 47389

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 26/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS GOH LAI PENG
ADDRESS : 27 EWE BOON ROAD
#09-01
SINGAPORE 259330
TELEPHONE : HP +65 94885396
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220055887
VEHICLE NO : SNA 782 E
MODEL CODE : AUDI Q2 1.5 TFSI S-TRONIC
MODEL YEAR : 25/5/2022
ENGINE NO : DPC D88228
CHASSIS NO : WAUZZZGA0NA011224
MILEAGE : 3,888
DATE IN : 25-Oct-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Oct-22
PLACE OF ACCIDENT : EWE BOON ROAD ALONG 15-27 HSE NOS

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 782 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00 ✓	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 250	
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. (p.h.h.)	S/N \$ 1,600.00 ✓	
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00 ✓	
5	TO RENEW RHS FRONT FENDER INNER AIRCON PIPE.	S/N \$ 280.00 X	
TOTAL LABOUR CHARGES		: \$ 3,840.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 782 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$ 280.00 /	
7	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT, TO REPAIR RHS FRONT FENDER TOP SUPPORT, BONNET, RHS UPPER A-PILLAR AND RHS FRONT DOOR. TO CUT OUT AND WELD RHS FRONT CHASSIS FRAME COVER PLATE. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 8,000.00 2.5 5.5 X 5.0	2750
8	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT FENDER TOP SUPPORT, RHS FRONT CHASSIS FRAME COVER PLATE, RHS UPPER A-PILLAR AND RHS FRONT DOOR.	\$ 5,500.00 5 X 5.0	2750
9	TO RENEW RHS FRONT RIM AND CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00 X	
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		\$ 18,332.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 782 E

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
1	FRONT BUMPER / BR	1	\$	1,390.00	✓	1112
2	FRONT BUMPER BRACKET - LH / RH / OR	1	\$	27.00	10.48	✓
3	FRONT BUMPER ADAPTER - RH / BR	1	\$	48.00	✓	37.76
4	FRONT BUMPER GRILLE - CENTER / OR	1	\$	220.00	✓	175.6
5	FRONT PARKING AID SENSOR SUPPORT - LH / RH / ms	1	\$	66.00	25.68	✓
6	FRONT BUMPER TRIM - RH / ms	1	\$	104.00	✓	83.2
7	FRONT BUMPER AIR GUIDE GRILLE - RH / BR	1	\$	101.00	✓	80.8
8	FRONT PARKING AID SENSOR SUPPORT - RH / ms	1	\$	33.00	✓	25.68
9	FRONT BUMPER GRILLE COVER - LOWER CENTER / ? X	1	\$ nn	18.00		
10	FRONT BUMPER LOWER TRIM / BR	1	\$	113.00	✓	90.4
11	FRONT BUMPER CLOSING ELEMENT / OR	1	\$	174.00	✓	138.8
12	FRONT WHEEL SPOILER - RH / CUT	1	\$	38.00	✓	30.24
13	FRONT BUMPER SPOILER / OR	1	\$	332.00	✓	265.6
14	FRONT BUMPER ADAPTER - RH / X nn	1	\$	48.00		
15	RADIATOR GRILLE / BR	1	\$	1,561.00	✓	1248.8
16	RADIATOR GRILLE STRIKER PLATE / ? BR	1	\$	212.00	✓	169.2
17	FRONT BUMPER FOAM FILLER PIECE / ? X nn	1	\$	87.00		
18	FRONT BUMPER REINFORCEMENT BEAM / BT	1	\$	769.00	✓	614.8
19	FRONT BUMPER GUIDE SECTION - RH / BR	1	\$	40.00	✓	31.84
20	FRONT BUMPER TOP COVER / BR	1	\$	112.00	✓	89.6
SUB TOTAL SPARE PARTS		:	\$	5,493.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 782 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	CAUTION SIGN STICKER / <i>mc</i>	1	\$ 16.00	✓ 12.4
22	AIR CONDITIONER STICKER / <i>mc</i>	1	\$ 9.00	✓ 6.64
23	ENGINE OIL STICKER X <i>nn</i>	1	\$ 13.00	
24	HORN HIGH TONE - RH / <i>OR</i>	1	\$ 162.00	✓ 129.2
25	HORN BRACKET - RH BT X <i>nn</i>	1	\$ 35.00	
26	FRONT FENDER - RH / <i>OR</i>	1	\$ 1,285.00	✓ 1028
27	FRONT FENDER ATTACHMENT PARTS X <i>nn</i>	1	\$ 42.00	
28	FRONT FENDER BRACKET - RH FRONT / <i>BT</i>	1	\$ 56.00	✓ 44.4
29	FRONT FENDER BRACKET - RH CENTER / <i>BT</i>	1	\$ 18.00	✓ 13.92
30	FRONT FENDER BRACKET - RH REAR ? <i>BT</i>	1	\$ 18.00	✓ 13.92
31	FRONT FENDER RIVET / <i>mc</i>	7	\$ 27.00	✓ 21.28
32	FRONT FENDER BRACKET FOR HEADLIGHTS ? X <i>nn</i>	1	\$ 26.00	
33	FRONT FENDER BRACE - RH ? <i>BT</i>	1	\$ 59.00	✓ 46.56
34	FRONT FENDER INSULATION - RH ? X <i>nn</i>	1	\$ 85.00	
35	FRONT FENDER CLOSING ELEMENT - RH ? X <i>nn</i>	1	\$ 37.00	
36	FRONT WHEEL HOUSING LINER - RH / <i>BR</i>	1	\$ 213.00	✓ 170
37	HEADLIGHT MOUNTING - RH / <i>BR</i>	1	\$ 132.00	✓ 105.2
38	HEADLIGHT - RH / <i>BR</i>	1	\$ 6,147.00	✓ 4917.6
39	HEADLIGHT HOSE - RH ? X <i>nn</i>	1	\$ 34.00	
40	HEADLIGHT COMPENSATING PIECE / <i>MIS</i>	1	\$ 53.00	✓ 42

SUB TOTAL SPARE PARTS

: \$ **8,467.00**

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 782 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	LIFT CYLINDER - RH ✓ BR	1	\$ 156.00 ✓	124.4
42	LIFT CYLINDER HOSE ✓ Th	1	\$ 89.00 ✓	70.48
43	LOCK CARRIER ✓ BR	1	\$ 1,101.00 ✓	880.8
44	A/C CONDENSER ? X nn	1	\$ 605.00	
45	A/C CONDENSER REFRIGERANT LINE ? BT	1	\$ 623.00 ✓	498.4
46	A/C CONDENSER REFRIGERANT LINE ? BT	1	\$ 500.00 ✓	400
47	A/C CONDENSER REFRIGERANT LINE ? X nn	1	\$ 570.00	
48	RADIATOR ? X nn	1	\$ 1,064.00	
49	ADDITIONAL RADIATOR ? ✓ BR	1	\$ 961.00 ✓	768.8
50	RADIATOR BRACKET - UPPER ✓ NEC	2	\$ 90.00 ✓	71.84
51	RADIATOR BUSH - LOWER ? NEC	2	\$ 22.00 ✓	16.96
52	RADIATOR AIR GUIDE - RH ? X nn	1	\$ 35.00	
53	READY-MIX COOLANT ✓ ncc	6	\$ 297.00 ✓	237.12
54	RADIATOR AIR GUIDE - RH ? BR	1	\$ 43.00 ✓	34.08
55	RADIATOR AIR GUIDE SEAL - RH OUTER ? X nn	1	\$ 8.00	
56	RADIATOR AIR GUIDE - UPPER CENTRE ? X nn	1	\$ 32.00	
57	AIR INTAKE UPPER COVER ? X nn	1	\$ 30.00	
58	AIR INTAKE AIR GUIDE - LOWER ? X nn	1	\$ 59.00	
59	AIR INTAKE AIR GUIDE - CENTER ? X nn	1	\$ 36.00	
60	AIR INTAKE AIR GUIDE - REAR ? X nn	1	\$ 36.00	
SUB TOTAL SPARE PARTS			:	\$ 6,357.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.




55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 782 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	AIR FILTER X nn	1	\$ 337.00	
62	RADIATOR WATER DRAINAGE HOSE X nn	1	\$ 37.00	
63	FRONT WHEEL COVER - LH / RH /	2	\$ 720.00	✓ 576
64	FRONT WINDSCREEN APERTURE SEAL - RH OUTER ? X	1	\$ nn 151.00	
65	FRONT WINDSCREEN GUIDE - RH X nn	1	\$ 459.00	
66	FRONT DOOR COVER - RH /	1	\$ 270.00	✓ 216
67	FRONT DOOR COVER PLATE - RH ? X nn	1	\$ 107.00	
68	FRONT ALUMINIUM RIM X nn	1	\$ 899.00	
69	FRONT ALUMINIUM RIM RUBBER VALVE X nn	1	\$ 4.00	
70	FRONT NO PLATE /	S/N	\$ 60.00	✓
71	SUNDRIES ? NEC		\$ 500.00	95.60 ✓
TOTAL SPARE PARTS			\$ 23,861.00	
TOTAL LABOUR CHARGES			\$ 18,332.00	
GRAND TOTAL			\$ 42,193.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

:
:
:
:
:
:

Stew (LKK)
26/10/22, 2.10P
OD-MAL
EXCIP-?
PIP, M BL Y, 11 dpr

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT