

REPAIR ESTIMATE*

DATE: 21.10.22
MVA JUMANI
DOA: 21.10.22

CLSUM)
INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY <i>le</i>			\$503.04
1	REAR BUMPER CENTRE MLDG <i>tn</i>			\$654.96
1	REAR BUMPER BEAM <i>x nn</i>			\$378.33
10	REAR BUMPER CLIPS <i>le</i>			\$22.00
1	TAILLAMP ASSY UPPER RH <i>x</i>			\$557.90
1	TAILLAMP ASSY LOWER RH <i>x</i>			\$570.00
1	SEAL- REAR BUMPER SIDE RH <i>x</i>			\$148.40
1	BRACKET - REAR BUMPER SIDE RH <i>x</i>			\$94.80
1	TOW COVER - REAR BUMPER <i>x</i>			\$82.70
	SUB TOTAL			\$3,012.03
	LESS 25%			\$730.03
	DISCOUNTED TOTAL			\$2,259.10
	REAR BUMPER MAT <i>le</i>			\$50.00
	ADVERTISEMENT LOGO - BUMPER <i>le</i>			\$50.00
	ADVERTISEMENT LOGO - FENDER <i>le</i>			\$200.00
				\$300.00
	Labour Charge			
	PANEL BEATING –			\$400.00
	SPRAY PAINT			\$300.00
	REMOVE/REFIX REVERSE SENSOR			\$50.00
	CHECK WIRING			\$50.00
	TOTAL LABOUR			\$800.00
	ESTIMATE TOTAL			\$3,359.10

2 Day 5.
4/5
Gmo by
2/10
3pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display the vehicle for resurvey
- To provide a written report
- Third party agreement on "no prejudice" basis
- No liability for damage to vehicle
- Company is not responsible for and is not an insurance company

Acknowledged by: _____ Date: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.