

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SH7557Y

Date: 18/10/2022

Make : HYUNDAI

Insurance: INCOME

Model : IONIQ(G3)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR DOOR LH X <i>by repair</i>			\$ 2,147.90
1	REAR FENDER LH X <i>by repair</i>			\$ 1,768.30
1	ROCKER COVER GARNISH LH ✓ <i>cut</i>			\$ 290.00
1	REAR FENDER GARNISH LH X			\$ 173.60
	SUB TOTAL			\$ 4,379.80
	LESS 20%			\$ 875.96
	DISCOUNTED TOTAL			\$ 3,503.84
	RR DOOR COMFORTDELGRO LOGO STICKER LH <i>✓</i>			\$ 80.00
	REAR FENDER "PETROL ONLY" STICKER <i>✓</i>			\$ 15.00
	RENEW ADVERTISEMENT LOGO <i>✓</i>			\$ 200.00
			Nett	\$ 295.00
	Labour Charge			
	PANEL BEATING			\$ 1,100.00
	SPRAY PAINTING CHARGE			\$ 1,000.00
	TUFF KOTE			\$ 60.00
	TRANSFER OF DOOR			\$ 120.00
	TOTAL LABOUR			\$ 2,280.00
	ESTIMATE TOTAL			\$ 6,078.84

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

4 Days
4/5
Gmo Ay
18/10
3pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display items to be repaired on resurvey
- Parts to be replaced on "as is" basis
- Third party claims on "no-fault" basis
- No payment for items not on "no-fault" basis
- Settlement of claims by LKK Auto Consultants and is subject to the insurance company's approval

Acknowledged by the Repairer:

Signature:

Date:

700
750
X
X sum