

ASS. RECD. BY:

REF:

LPC / 22010622/KCP

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 810K

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 05 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 04/23

Person Contacted: _____

Vehicle: IN / OUT

Veh No: STL 4171GYr Regn: 11, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: Honda Freedc.c. 1496Colour: M. Brown

A/C: Insured / Std / NI / NA

Sp. Reading: 290173

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GB3

1025009

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / SR / STD A/Rim orTyre Size: F: Rapid 195/55R15R: Goodride

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 7 mmR/Bal. 4 mmL/Bal. 7 mmL/Bal. 4 mmD.O.A. 21/10/22D.O.I. 27/10/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

9/11 21Pm @ 4300L Conhr

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SJL4171G
TP/Lonpac

M/S : LONPAC INSURANCE BERHAD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

TEL: 62507388 FAX: 62963767
ATTN: Motor Claim Department

WS Ref: TP/LONPAC
Claim Type: Third Party
Accident Date: 21/10/2022
TP Veh Reg No: YP1980J

Not Authorized
11 Rmp @ 4300p
Recovery After Paint
5 days

Estimate No: ES2291098/WS
Date: 25 Oct 2022
Policy No: DMPCSNW00105002201
Veh Reg No: SJL4171G
Make/Model: HONDA HONDA FREED
1.5G A
Chassis No: GB31025009
Engine No: L15A2325316
Reg. Date: 26/11/2008

Estimate Repair Cost to Vehicle No :SJL4171G

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	490.30	1 PC	490.30	✓
2 REAR BUMPER BEAM	56.20	1 PC	56.20	✓
3 REAR BUMPER CLIPS	3.90	6 PCS	23.40	✓
4 REAR TAILGATE	1,282.50	1 PC	1,282.50	✓
5 TAILGATE LOGO	29.40	1 PC	29.40	✓
6 TAILGATE EMBLEM (FREED)	48.30	1 PC	48.30	✓
7 TAILGATE INNER LOCK	189.50	1 PC	189.50	✓
8 TAILGATE INNER RUBBER	95.00	1 PC	95.00	✓
9 TAILGATE OUTER CENTRE GARNISH	287.30	1 PC	287.30	✓
10 TAILLAMPS	402.30	2 PCS	804.60	✓
11 REAR WINDSCREEN GLASS	1,144.60	1 PC	1,144.60	✓
12 REAR WINDSCREEN GLASS MOULDING	131.80	1 PC	131.80	✓
13 REAR PANEL	342.90	1 PC	342.90	✓
14 REAR WIPER ARM	45.00	1 PC	45.00	✓
15 REAR WIPER MOTOR	280.80	1 PC	280.80	✓
			5,251.60	
		Less 20%	1,050.32	4,201.28
Special Net				
16 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
17 REVERSE SENSOR	200.00	1 SET	200.00	✓
			240.00	240.00
Labour				
18 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
19 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, TAILGATE, LOCK ASSY, REAR WIPER ASSY, KNOCK & REPAIR REAR PANEL, TAILLAMP PANEL AND REALIGN THE SAME	600.00	1 LA	600.00	550/
20 PUTTY & RESPRAY ON REAR BUMPER, TAILGATE, REAR PANEL AND REAR AFFECTED AREAS	650.00	1 LA	650.00	600/
21 REMOVE & REFIX REVERSE CAMERA & SENSOR AND RESET SYSTEM	40.00	1 LA	40.00	✓
22 RUSTPROOFING	30.00	1 LA	30.00	✓
			1,420.00	1,420.00
			Total	S\$ 5,861.28
			Add GST @ 7%	410.29
			Total Amount Payable	S\$ 6,271.57

Date: _____
Signature: _____
Acknowledged by Repairer

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE