

KGC WORKSHOP PTE LTD

Since 1967

Sincere • Secure • Satisfaction

TSL Electrical Services
14 Ang Mo Kio St 63
Block B
Singapore 569116

Registration No : GBL 4894Z
Accident Date : 21-Oct-22
Our Ref : TP

UKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Date 25/10/2022
No of Page : 1/1

Model : TOYOTA HIACE 2.0 DX
Chassis No: TRH2005047128
Engine Capacity 2

S/No	Qty	Items	Unit Price	Amount
1	1	Bonnet	\$ 275.00	\$ 275.00
2	1	Bonnet Emblem	\$ 35.00	\$ 35.00
3	1	Front Center Grille(upper)	\$ 190.00	\$ 190.00
4	1	Front Center Grille(middle)	\$ 320.00	\$ 320.00
5	1	Front Center Grille base	\$ 285.00	\$ 285.00
6	1	Front Lower Grille Cover LHS	\$ 55.00	\$ 55.00
7	1	Front Bumper	\$ 240.00	\$ 240.00
8	1	Front Bumper reinforcement	\$ 175.00	\$ 175.00
9	2	Front Bumper retainer RHS/LHS	\$ 60.00	\$ 120.00
10	2	Headlamp RHS/LHS (LED)	\$ 850.00	\$ 1,700.00
11	1	Condenser	\$ 500.00	\$ 500.00
12	1	Radiator	\$ 490.00	\$ 490.00
			\$	4,385.00
			cost plus 10%	\$ 438.50
			Total for spare parts	\$ 4,823.50

Special Nett

1	1 set	Front Bumper Clips	\$ 50.00	\$ 50.00
2	1	Front Number Plate	\$ 50.00	\$ 50.00
			Total for SP	\$ 100.00
			Sub-Total for Parts :	\$ 4,923.50

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mention repair parts, inclusive of replacement parts.		400 900.00
2		To putty and spray paint on all accident damage parts and other accident affected areas		400 800.00
3		Mechanic Labour to remove and refit condenser and radiator		100? 220.00
4		top up aircon gas		✓ 80.00
5		top up coolant		X 80.00
6		To check wiring system to facilitate repair and refit the same		30? 80.00

Taufik 97495749

Not Authorise

28/10/22

Plp Resurvey before paint
4 days

TOTAL AMOUNT : 2,160.00
OVERALL COST : 7,083.50