

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22010636/UNY3E2
Date: 22/02/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SPMF1000000537
Claimant Vehicle No : SNC8682Y **Insured Vehicle No :** YQ7717J
 Date of Loss: 22/10/2022 Nature of Claim: TP Claim No: SVRAISCL2022-00064

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNC8682Y**
 Make & Model: RENAULT GRAND SCENIC IV, 1.5 DCI EU6 (A) Engine No: K9KF649D020495
 Reg. Date: 11/05/2018 (Man. Year: 2017) Chassis No: VF1RFA00859238272
 Colour: Black Odometer: 135247 km
 Engine Capacity: 1461 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R20 Rear Tyre Size: 195/55 R20
 Front Left Side: Triangle 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Triangle 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,701.27	14,426.57	5,274.70	26.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,540.00	2,580.00	1,960.00	43.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,241.27	17,006.57	7,234.70	29.84
Approved Total (Overridden) (S\$)		13,600.00		
(S\$)	24,241.27	13,600.00	10,641.27	43.90
+ GST 8.00/8.00% (S\$)	1,939.30	1,088.00	851.30	43.90
Nett Amount (S\$)	26,180.57	14,688.00	11,492.57	43.90
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 27/10/2022
 Date Inspected: 09/11/2022 Inspected At: Precise Auto Service (HQ)
 No 1 Kaki Bukit Ave 6, #02-34/36
 Singapore 417883
 Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Feb 2023)
Parts:	M1-MPV	RENAULT GRAND SCENIC IV 1.5 DCI EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC8682Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*SIDE MIRROR ASSY LH	Broken	1,400.00 FL	*1,215.00 FL
2	1	*FRONT DOOR LH	Badly Dented	1,800.00 FL	*1,800.00 FL
3	2	*FRONT DOOR HINGE (TOP & BOTTOM)	Bent	500.00 FL	*320.00 FL
4	1	*FRONT DOOR CHECKER	Twisted	250.00 FL	*181.00 FL
5	1	*FRONT DOOR PROTECTOR	Grazed	600.00 FL	*600.00 FL
6	1	*FRONT DOOR OUTER HANDLE	Cut	300.00 FL	*300.00 FL
7	1	*FRONT DOOR OUTER HANDLE KNOB	Cut	95.00 FL	*95.00 FL
8	1	*FRONT DOOR OUTER HANDLE BRACKET	Not Necessary	250.00 FL	*- FL
9	1	*FRONT DOOR INNER LOCK	Damaged / Jammed	400.00 FL	*400.00 FL
10	1	*FRONT DOOR STOPPER	Not Necessary	100.00 FL	*- FL
11	1	*FRONT DOOR WEATHERSTRIPE	Necessary	300.00 FL	*300.00 FL
12	1	*FRONT DOOR BOTTOM RUBBER BEADING	Torn	200.00 FL	*200.00 FL
13	1	*FRONT DOOR INNER HANDLE CABLE	Not Necessary	180.00 FL	*- FL
14	1	*FRONT DOOR INNER TRIM BOARD	Deformed / Torn	650.00 FL	*650.00 FL
15	8	*FRONT DOOR INNER TRIM BOARD CLIPS	Not Necessary	72.00 FL	*- FL
16	1	*FRONT DOOR SPEAKER	Cracked	600.00 FL	*358.00 FL
17	2	*FRONT DOOR WINDOW GLASS CHANNEL (FRONT & REAR)	Not Necessary	900.00 FL	*- FL
18	2	*FRONT DOOR WINDOW GLASS CHANNEL RUBBER	Not Necessary	380.00 FL	*- FL
19	1	*FRONT DOOR WINDOW REGULATOR WITH MOTOR	Bent / Jammed	800.00 FL	*800.00 FL
20	1	*FRONT DOOR WINDOW GLASS OUTER MOULDING	Necessary	280.00 FL	*280.00 FL
21	1	*FRONT DOOR INNER DUST COVER	Not Necessary	55.00 FL	*- FL
22	1	*REAR DOOR LH	Badly Dented	1,750.00 FL	*1,750.00 FL
23	2	*REAR DOOR HINGE (TOP & BOTTOM)	Bent	500.00 FL	*320.00 FL
24	1	*REAR DOOR CHECKER	Twisted	250.00 FL	*181.00 FL
25	1	*REAR DOOR PROTECTOR	Grazed	580.00 FL	*580.00 FL
26	1	*REAR DOOR INNER LOCK	Damaged / Shorted	400.00 FL	*400.00 FL
27	1	*REAR DOOR WEATHERSTRIPE	Necessary	280.00 FL	*280.00 FL
28	1	*REAR DOOR STOPPER	Not Necessary	100.00 FL	*- FL
29	1	*REAR DOOR OUTER HANDLE	Cut	300.00 FL	*300.00 FL
30	1	*REAR DOOR OUTER HANDLE KNOB	Cut	95.08 FL	*95.08 FL
31	1	*REAR DOOR OUTER HANDLE BRACKET	Not Necessary	250.00 FL	*- FL
32	1	*REAR DOOR SPEAKER	Not Necessary	600.00 FL	*- FL
33	1	*REAR DOOR INNER TRIM BOARD	Deformed / Torn	600.00 FL	*600.00 FL
34	8	*REAR DOOR INNER TRIM BOARD CLIPS	Not Necessary	72.00 FL	*- FL
35	1	*REAR DOOR CENTER PILLAR (OUTER)	Dented	690.00 FL	*690.00 FL
36	1	*REAR DOOR VERTICAL GARNISH (TOP)	Not Necessary	300.00 FL	*- FL
37	1	*REAR DOOR VERTICAL BOTTOM GARNISH	Not Necessary	300.00 FL	*- FL
38	1	*REAR DOOR INNER HANDLE CABLE	Not Necessary	180.00 FL	*- FL
39	1	*REAR DOOR INNER DUST COVER	Not Necessary	55.00 FL	*- FL
40	1	*REAR FENDER LH	Dented / Bent	2,200.00 FL	*2,200.00 FL
41	1	*REAR FENDER GLASS MOULDING	Necessary	400.00 FL	*400.00 FL
42	8	*REAR FENDER GLASS CLIPS	Not Necessary	72.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*ROCKER PANEL GARNISH LH	Grazed	690.00 FL	*690.00 FL
44	8		*ROCKER PANEL GARNISH CLIPS	Not Necessary	72.00 FL	*- FL
45	1		*REAR LH SPORT RIM ASSY	Repair	920.00 FL	*- FL
46	1		*REAR FENDER GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
47	1		*REAR FENDER GLASS INNER SEAL	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	21,878.08	16,025.08
- List Item Discount on L Items 10.00/10.00% (\$)	2,176.81	1,598.51
Total Parts (\$)	19,701.27	14,426.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	100.00	0.00
2	TO CHECK WIRING SYSTEM	New	120.00	20.00
3	TO REMOVE & REFIX INTERIOR UPHOLSTERY	New	150.00	80.00
4	TO REMOVE & REFIX REAR LH FENDER GLASS	New	150.00	100.00
5	TO CHECK & ADJUST COMPUTER WHEEL ALIGNMENT	New	120.00	60.00
6	TO REMOVE & REFIX REAR LH SPORT RIM & CONTACT WHEEL BALANCING	New	120.00	0.00
7	TO REMOVE & REFIX FRONT REAR LH DOOR MECHANISM	New	400.00	120.00
8	TO RESET ELECTRICAL MODULE SYSTEM	New	380.00	0.00
9	TO RENEW DAMAGED PARTS, STRAIGHTEN & REPAIR, FRONT LH FENDER, REAR BUMPER ALIGNED ALL PARTS	New	1,500.00	1,200.00
10	TO RESPRAY AFFECTED AREAS	New	1,500.00	1,000.00
Gross Labour Cost (\$\$)			4,540.00	2,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >