

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 20 Dec 2022

Preliminary Advice

Vehicle No	: SNG7416K	Accident Date	: 20/10/2022
Make	: MINI COOPER	Policy No.	: SP2002787392-01
Assignment Date	: 27/10/2022	Excess	: S\$600.00
Date of Inspection	: 27/10/2022	Est. Duration of Repair	: 12
Inspection At	: SME MOTOR PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	46,977.20	(Estimate \$43,655.20 + Supplementary \$3,322.00)
Revised Amount	:S\$	35,811.60	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	35,811.60	
Lump Sum Repair	:S\$	25,000.00	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	24,683.00
Salvage Value	:S\$	
Margin for Repair	:S\$	43,317.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.