

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	22/AL/OD-519(10)
Policy No:	SP2002787392-01	Date of Loss:	20/10/2022
Vehicle Reg. No.:	SNG7416K	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	KEEFE CHUA JUN XIANG		
Make/Model:	MINI COOPER, 1.6 (A)	Vehicle Reg. Date:	22/11/2010
Vehicle Colour:	WHITE	Chassis No:	MWNSV32020TY82387
Engine No:	B233I828		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Remarks:	VEHICLE IN, KINDLY ARRANGE FOR SURVEY.		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

COST OF CLAIMS

	Amount
Parts	36,995.20
Miscellaneous Items	700.00
Labour	5,960.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	43,655.20
+ GST 7.00% (S\$)	3,055.86
Nett Amount (S\$)	46,711.06

This claim is handled by: **WEN YING**

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorised
am
Excess \$600
1/5 \$
12 days
to be photo after repair

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Oct 2022)
Parts: M1-COUPE MINI COOPER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SNG7416K)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT WINDSCREEN	0.00	0.00	CNE *650.00 F ✓
2	1		*FRT WINDSCREEN MOULDING	0.00	0.00	HEL *60.00 F ✓
3	1		*FRT BONNET	0.00	0.00	BUC *1,100.00 F ✓
4	2		*FRT BONNET HINGES	0.00	0.00	N *190.00 F X
5	1		*FRT BONNET LOCK	0.00	0.00	QW *100.00 F ✓
6	1		*FRT BONNET SCOOP	0.00	0.00	CNE *230.00 F ✓
7	1		*FRT BONNET MOULDING	0.00	0.00	CNE *135.00 F ✓
8	1		*FRT BONNET CENTRE LOGO	0.00	0.00	HEL *95.00 F ✓
9	1		*FRT GRILLE	0.00	0.00	CNE *145.00 F ✓
10	1		*FRT BONNET TRIM	0.00	0.00	NK *220.00 F X
11	1		*FRT BUMPER	0.00	0.00	D15 *780.00 F ✓
12	1		*FRT BUMPER RETAINER RH	0.00	0.00	CNE *50.00 F ✓
13	10		*FRT BUMPER CLIPS	0.00	0.00	HEL *20.00 F ✓
14	1		*FRT BUMPER TOW COVER	0.00	0.00	QW *50.00 F ✓
15	1		*FRT BUMPER LOWER GRILLE	0.00	0.00	QW *125.00 F ✓
16	1		*FRT BUMPER REINFORCEMENT	0.00	0.00	BUT *450.00 F ✓
17	1		*RH FOG LAMP	0.00	0.00	QW *195.00 F ✓
18	1		*RH FOG LAMP GARNISH	0.00	0.00	BRO *105.00 F ✓
19	1		*RH HEADLAMP	0.00	0.00	QW *800.00 F ✓
20	1		*RH HEADLAMP RIM	0.00	0.00	BRO *95.00 F ✓
21	1		*RH HEADLAMP NPPZLE	0.00	0.00	BRO *105.00 F ✓
22	1		*RH HEADLAMP NOOZLE COVER	0.00	0.00	TOM *45.00 F ✓
23	1		*HEADLAMP NOOZLE HOSE	0.00	0.00	TOM *80.00 F ✓
24	1		*HEADLAMP SUPPORT PANEL	0.00	0.00	CNE *650.00 F ✓
25	1		*AIRCON CONDENSER	0.00	0.00	*620.00 F ?
26	1		*RADIATOR	0.00	0.00	*600.00 F ?
27	1		*RADIATOR LOWER HOSE	0.00	0.00	*145.00 F ?
28	1		*AIRCON LIQUID PIPE	0.00	0.00	*160.00 F ?
29	1		*AIRCON DISCHARGE PIPE	0.00	0.00	*185.00 F ?
30	1		*FRT RH FENDER	0.00	0.00	D15 *980.00 F ✓
31	1		*FRT RH FENDER INNER COWLING	0.00	0.00	TOM *230.00 F ✓
32	10		*INNER COWLING CLIPS	0.00	0.00	HEL *30.00 F ✓
33	1		*FRT RH FENDER OUTER TRIM	0.00	0.00	D15 *250.00 F ✓
34	1		*FRT RH FENDER SIGNAL LAMP	0.00	0.00	*95.00 F ?
35	1		*FRT RH FENDER PROTECTOR	0.00	0.00	*185.00 F
36	2		*FRT BUMPER PROTECTOR	0.00	0.00	*320.00 F
37	1		*FRT RH SHOCK ABSORBER	0.00	0.00	*250.00 F ?
38	1		*FRT RH LOWER ARM	0.00	0.00	BUT *280.00 F ✓
39	1		*FRT RH KNUCKLE ARM	0.00	0.00	BUT *380.00 F ✓
40	1		*FRT RH KNUCKLE BEARING	0.00	0.00	HEL *260.00 F ✓
41	1		*FRT RH DRIVE SHAFT	0.00	0.00	BRO *1,650.00 F ✓
42	1		*STEERING RACK ASSY	0.00	0.00	BUT *3,950.00 F ✓
43	1		*STEERING CROSSMEMBER	0.00	0.00	*1,250.00 F ?
44	1		*FRT RH ABS SENSOR	0.00	0.00	*175.00 F ?
45	1		*ANTI ROLL BAR LINK RH	0.00	0.00	BUT *90.00 F ✓
46	1		*FRT ANTI ROLL BAR	0.00	0.00	*250.00 F ?
47	1		*FRT RH WHEEL HOUSING PANEL	0.00	0.00	R *980.00 F X
48	1		*FRT RH DOOR PILLAR	0.00	0.00	*2,200.00 F ?
49	1		*STEERING AIRBAG	0.00	0.00	BUT *950.00 F ✓
50	1		*AIRBAG CONTROL UNIT	0.00	0.00	BUT *950.00 F ✓
51	1		*CLOCK SENSOR	0.00	0.00	BUT *800.00 F ✓
52	1		*FRT RH AIRBAG SENSOR	0.00	0.00	BUT *195.00 F ✓
53	2		*FRT SAFETY BELT	0.00	0.00	*760.00 F ?
54	1		*DASHBOARD	0.00	0.00	BUS *980.00 F ✓
55	1		*FRT RH FENDER TOP MOULDING	0.00	0.00	HEL *190.00 F X
56	1		*RH SIDE SKIRT	0.00	0.00	D15 *3,000.00 F ✓
57	1		*RH SIDE SKIRT CLIPS	0.00	0.00	HEL *3.00 F ✓
58	1		*RH SIDE SKIRTS PROTECTOR	0.00	0.00	D15 *125.00 F ✓
59	1		*FAN BELT	0.00	0.00	*65.00 F ?

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
60	1		*ENGINE MOUNTING	0.00	0.00	*550.00 F	?
61	1		*AIRCON COMPRESSOR	0.00	0.00	*1,250.00 F	?
62	2		*ENGINE UNDER COVER	0.00	0.00	*390.00 F	X
63	8		*UNDER COVER CLIPS	0.00	0.00	*24.00 F	X
64	1		*WIPPER GARNISH	0.00	0.00	*110.00 F	X
65	1		*FRT PASSENGER AIRBAG	0.00	0.00	*1,300.00 F	X
							<i>NF</i>
							<i>11</i>
							<i>11</i>
							<i>Added</i>
Sub Total (\$\$)						33,632.00	
+ Margin on L,N Items 10.00% (\$\$)						3,363.20	
Total Parts (\$\$)						36,995.20	

F=Franchise part.

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	ERP BRACKET <i>del</i>	25.00 <i>15</i>
2	1	FRT RH SPORT RIM <i>one</i>	300.00 ✓
3	1	FRT RH TYRE	250.00 ?
4	1	FRT WINDSCREEN GUM <i>del</i>	60.00 <i>40</i>
5	1	NUMBER PLATE <i>?</i>	40.00 ?
6	1	RADIATOR COOLANT <i>in</i>	25.00 ✓
Sub Total (\$\$)			700.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	WIRE CHECKING	New	30.00 ✓
2	REMOVE & REFIX AIRCON AND GAS	New	100.00 ✓
3	REMOVE & REFIX FRT UNDER CARRRIAGE (WITH RACK AND CROSSMEMBER)	New	350.00 ✓
4	4 WHEEL ALIGNMENT	New <i>70</i>	80.00 -
5	REMOVE & REFIX AIRCON COMPRESSOR & 1 SET ENGINE MOUNTING	New <i>?</i>	250.00
6	REMOVE & REFIX FRT WINDSCREEN	New	120.00 ✓
7	REMOVE & REFIX 2 PCS SAFETY BELT AND AIRBAG SYSTEM	New <i>?</i>	350.00
8	REMOVE & REFIX DASHBOARD	New <i>250</i>	280.00
9	REPROGRAMME AIRBAG SYSTEM	New <i>200</i>	300.00
10	REPAIR WIRE HARNESS	New <i>80</i>	120.00
11	REMOVE & REFIX CUSHION AND SEATS	New <i>11</i>	180.00 X
12	LABOUR CHARGE	New <i>1400</i>	2,200.00
13	SPRAY PAINTING	New <i>1000</i>	1,600.00
Gross Labour Cost (\$\$)			5,960.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >