

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jenny Lew

Date: 28 Oct 2022

Preliminary Advice

Vehicle No	: SMQ7045G	Accident Date	: 22/10/2022
Make	: HYUNDAI AVANTE	Policy No.	: DMPCSNW00239062100
Assignment Date	: 27/10/2022	Excess	: S\$500.00
Date of Inspection	: 28/10/2022	Est. Duration of Repair	: 5
Inspection At	: CHIN NAM HUP KEE MOTOR WORKS PTE LTD (HQ) 14 SIN MING DRIVE #17-18/19 SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,717.20
Revised Amount	:S\$	3,907.20
Check Items (Estimated)	:S\$	1,282.80
Total	:S\$	5,190.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 81,000.00
COE / PARF Rebate	:S\$ 35,321.00

Salvage Value	:S\$
Margin for Repair	:S\$ 45,679.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PLEASE TAKE NOTE THAT THE REPAIRER PUT UP COST PLUS 20%.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.