

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/ASM22010643/Upa3

ASSIGNMENT

From: Date:

Estimated Cost:

OD ☒ TP ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$)

☐

Preli. Report

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Dep 1600 N04488595

19/11/22 4/5 @ 2800 cabnet MR 700.

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Mohamad Faizal Bin Mohamed
Abedin (92252542)

Accident Date : 05-Sep-22

Vehicle No : FBQ1462E (010829)

Vehicle Model : Yamaha
MTN155

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender <i>cu7</i>	\$ 105 135.00 ✓
2	Fork tune assy - L/R <i>17</i>	\$ 980.00 X
1	Fork under bracket <i>17</i>	\$ 285.00 X
1	Front sport rim <i>major</i>	\$ 420.00 ✓
1	Front rim shaft <i>50</i>	\$ 145.00 X
1	Front rim bearing <i>1er</i>	\$ 50 105.00 ✓
1	Front brake disc <i>17</i>	\$ 235.00 X
1	Windshield <i>one</i>	\$ 220 385.00 ✓
1	Handle-bar <i>300</i>	\$ 250 385.00 ✓
1	Handle-bar end (1 set) <i>150 100</i>	\$ 40 155.00 ✓
1	Hand-grip (1 set) <i>15 70-1</i>	\$ 75 95.00 ✓
1	Side mirror (1 set) <i>15 50</i>	\$ 80 180.00 ✓
1	Clutch lever (1 set) <i>15 one</i>	\$ 125 190.00 ✓
1	Front signal (1 set) <i>15 30</i>	\$ 60 140.00 ✓
1	Headlamp cover <i>cu7</i>	\$ 185.00 ✓
1	Side cowling - matt <i>cu7</i>	\$ 145 225.00 ✓
1	Front side lower cover <i>cu7</i>	\$ 90 175.00 ✓
1	Fuel tank side cover - L/H <i>cu7</i>	\$ 255.00 ✓
2	Front footrest <i>15 30</i>	\$ 60 180.00 120
2	Front footrest brackets <i>15 one</i>	\$ 145 450.00 120
1	Gear pedal <i>300</i>	\$ 110 135.00 ✓
2	Rear footrests <i>15 cu7</i>	\$ 60 180.00 120
2	Rear footrest brackets <i>15 15 cu7</i>	\$ 180 480.00 120
1	Rear side cover - L/H <i>one</i>	\$ 285.00 ✓
1	Side stand <i>2</i>	\$ 125.00 X
1	Rear signals (1 set) <i>cu7</i>	\$ 60 140.00 ✓
		\$ 6,650.00
	Less 10%	\$ 665.00
		\$ 5,985.00

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Mohamad Faizal Bin Mohamed
Abedin (92252542)

Accident Date : 05-Sep-22

Vehicle No : FBQ1462E (010829)

Vehicle Model : Yamaha
MTN155

Estimated Repair Costs

<u>Special Net Items</u>				
1	Number plate	2nd set	\$	38.00 10
2	Fork oils	11	\$	30.00 X
2	Fork oil seals	11	\$	56.00 X
1	Steering cone (1 set)	11	\$	95.00 X
1	E.R.P. IU	165	\$	180.00 165
1	Rear box	600	\$	480.00 350
1	Rear box bracket	11	\$	180.00 X
1	MT-15 sticker set	11	\$	150.00 10
			\$	1,209.00

<u>S/No.</u>	<u>Labour</u>			
1	To provide towing service (LOD) S\$50.00		\$	-
2	To remove, refit and align body frame	11	\$	380.00 X
3	To check wiring and reset headlamp focusing	11	\$	80.00 X
4	To provide labour		\$	400.00 300
			\$	860.00

Grand Total

\$ 8,054.00

Singapore Dollars: Eight Thousand and Fifty-Four only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2- 3000
102
2700
605
300
3605