



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22010644/Uvy3m4	
			Date: 30/12/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 4973K	Veh. Inspected	SNC 7269P	
Policy No.	D22MTHCVE000675	Coverage (\$)	0.00	
Claim No.	CMTD2203868/SYH	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	26/10/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ 300SL (A)	c.c	2960	
Engine No.	HIDDEN	Year of Reg.	1990	
Chassis No.	WDB1290602F015521	Colour	BLACK	
Odometer	282841 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/35 R19	TOYO	6 mm	
L/H Front Tyre	245/35 R19	TOYO	6 mm	
R/H Rear Tyre	275/30 R19	TOYO	6 mm	
L/H Rear Tyre	275/30 R19	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/10/2022	Inspection Date	27/10/2022	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	