

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd 64 Cecil Street #04-00 IOB Building Singapore 049711	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
---------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------

Attn: Derrick Tan Ming Chye

Date: 28 Oct 2022

Preliminary Advice

Vehicle No	: SMG4727U	Accident Date	: 11/10/2022
Make	: MAZDA 3	Policy No.	: D18MFL0003414_03
Assignment Date	: 27/10/2022	Excess	: S\$0.00
Date of Inspection	: 28/10/2022	Est. Duration of Repair	: 9
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL) 205 BRADDELL ROAD SINGAPORE 579701		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 25,188.52
Revised Amount	:S\$ 20,361.56
Check Items (Estimated)	:S\$ 3,025.36
Total	:S\$ 23,386.92

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 78,000.00
COE / PARF Rebate	:S\$ 28,039.00

Salvage Value	:S\$
Margin for Repair	:S\$ 49,961.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.