

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

05-12-22

Date Of Accident : 25-10-2022

OUR REF : SNG 4058E/T/22

LKK - Morcos

AMARAVADI SANDHYA MOORTHY

Blk 1 Rivervale Link

#02-16

Singapore 545118

Date In/out: 26/10/22 to 01/11/22

ESTIMATE BILL ON VEH. NO. : SNG 4058E

MODEL : SUBARU IMPREZA

CHASSIS NO. : JF1GE3KF39G003983

LIST ITEM

Front Bumper		680.00
Front Bumper Side Retainer - RH		26.00
Front Bumper Clips	10pcs @ 3.20	32.00
Front Bumper Bracket - RH		44.00
Head Lamp Lower Bracket		64.00
		846.00
	Less Discount 20%:	169.20
		676.80

SPECIAL NETT ITEM

Head Lamp Sticket (Acc)	80.00
-------------------------	-------

LABOUR CHARGE

To Check Wiring System.	80.00
To Respray Affected Areas.	800.00
To Renew Damaged Parts, Straighten & Repair Frotn RH Fender, Front Support Panel & Aligned All Parts.	650.00
	2,286.80
	GST 7% : 160.08
TOTAL AMOUNT :	2,446.88