

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO.: 35766600C

GST REG. NO.: 35766600C

05-12-22

Date Of Accident : 25-10-2022

OUR REF : SNG 4058E/T/22

AMARAVADI SANDHYA MOORTHY

Blk 1 Rivervale Link

#02-16

Singapore 545118

LKK - Mercedes

Date In/out: 26/10/22 to 01/11/22

Not Acknowledged

2/5/2000
3 days

ESTIMATE BILL ON VEH. NO. : SNG 4058E

MODEL : SUBARU IMPREZA

CHASSIS NO. : JF1GE3KF39G003983

LIST ITEM

Front Bumper

80 680.00 /

Front Bumper Side Retainer - RH

26 26.00 /

Front Bumper Clips

10pcs @ 3.20

32 32.00 /

Front Bumper Bracket - RH

44 44.00 X

Head Lamp Lower Bracket

64 64.00 /

846.00

Less Discount 20%:

169.20

676.80

SPECIAL NETT ITEM

Head Lamp Sticket (Acc)

80 80.00 50

LABOUR CHARGE

To Check Wiring System.

80 80.00 20

To Respray Affected Areas.

800 800.00 500

To Renew Damaged Parts, Straighten & Repair Frotn RH Fender,
Front Support Panel & Aligned All Parts.

650 650.00 300

2,286.80

GST 7% :

160.08

TOTAL AMOUNT :

2,446.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: