



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SMH95E
Chassis No : MRHFC5650KT000581
Model : CIVIC 1.6 VTI YM2019
Owner's Name : LOY CHEE MENG
Ins Policy No. :
Date of Accident : 22/10/2022

Document No. : SQT22003120 Page 1
Date : 25. Oct 2022
Customer No. : WZF002
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : R16B25510614
Date | Time : 25. Oct 2022 11:51:53 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: LOY CHEE MENG OWNER INSURER: SOMPO ACC DATE: 25/10/2022 SURVEYED BY: DATE: REF NO: TP INSURER: FIRST CAPITAL TP VEH:						
68500-TEA-305ZZ	LID COMP,TRUNK	1	724.70	25	543.52	38.05	581.57
68610-TEA-T10ZZ	HINGE COMPR.TRUNK	1	51.60	25	38.70	2.71	41.41
68660-TEA-T10ZZ	HINGE COMPL.TRUNK	1	51.60	25	38.70	2.71	41.41
74851-TEA-003	LOCK ASSYTRUNK	1	85.80	25	64.35	4.50	68.85
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	1	116.10	25	87.07	6.09	93.16
75701-TBA-A10	EMBLEM,H-MARK	1	14.10	25	10.57	0.74	11.31
90301-ST0-003	NUT,PUSH 3MM	2	2.10	25	3.15	0.22	3.37
08F13-TEA-7T0AX-1	TRUNK SPOILER,WING TYPE	1	700.00	10	630.00	44.10	674.10
75701-TGH-A01	EMBLEM,RR.H	1	50.50	25	37.87	2.65	40.52
75725-TEA-T01	EMBLEMRR.	1	12.70	25	9.52	0.67	10.19
84620-TEA-Z11ZA	LINING ASSYTRUNK LID	1	38.10	25	28.57	2.00	30.57
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	10	2.30	25	17.25	1.21	18.46
71510-TEA-T50	GARNISH ASSY,RR.BUMPER LOWER	1	129.90	25	97.42	6.82	104.24
71503-TEA-T00	GARNISH,R.RR.BUMPER SIDE	1	9.00	25	6.75	0.47	7.22
71504-TBA-A00	COVERR.FINISHER	1	13.00	25	9.75	0.68	10.43

Printed on 26/10/2022 10:48:29 AM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn Bhd, it will be refunded

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SMH95E
Chassis No : MRHFC5650KT000581
Model : CIVIC 1.6 VTI YM2019
Owner's Name : LOY CHEE MENG
Ins Policy No. :
Date of Accident : 22/10/2022

Document No. : SQT22003120 **Page** 2
Date : 25. Oct 2022
Customer No. : WZF002
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : R16B25510614
Date | Time : 25. Oct 2022 11:51:53 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	190.10	25	142.57	9.98	152.55
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	1	2.50	25	1.87	0.13	2.00
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	1	2.50	25	1.87	0.13	2.00
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	1	50.30	25	37.72	2.64	40.36
84542-TET-H00	BOX COMPTOOL	1	44.00	25	33.00	2.31	35.31
84651-TEA-Q02ZA	LINING ASSY,L.TRUNK SIDE	1	56.30	25	42.22	2.96	45.18
66100-TEC-307ZZ	PANEL SETRR.	1	280.70	25	210.52	14.74	225.26
66501-TEA-T00ZZ	STIFFENERRR.SHELF FR.	1	48.90	25	36.67	2.57	39.24
65550-TEA-T00ZZ	PAN COMPSPARE TIRE	1	250.00	25	187.50	13.13	200.63
04636-TEA-T00ZZ	PANEL SETR.RR.OUTSIDE	1	821.40	25	616.05	43.12	659.17
04646-TEA-T00ZZ	PANEL SETL.RR.OUTSIDE	1	821.40	25	616.05	43.12	659.17
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
33500-TEA-T01	TAILLIGHT ASSYR.	1	301.70	25	226.27	15.84	242.11
33550-TEA-T01	TAILLIGHT ASSYL.	1	324.70	25	243.52	17.05	260.57
34100-TEA-T11	LIGHT ASSYLICENSE	1	72.60	25	54.45	3.81	58.26
34150-TEX-Y01	LIGHT ASSYR.LID	1	141.10	25	105.82	7.41	113.23
Sum Item					5076.93	355.39	5,432.32

BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00		450.00	31.50	481.50
BKTRR	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	1	450.00		450.00	31.50	481.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00		450.00	31.50	481.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00		450.00	31.50	481.50
BOJSE	BODY JOINT SEALANT END PANEL	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT TAILGATE	1	100.00		100.00	7.00	107.00

Printed on 26/10/2022 10:48:29 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SMH95E
Chassis No : MRHFC5650KT000581
Model : CIVIC 1.6 VTI YM2019
Owner's Name : LOY CHEE MENG
Ins Policy No. :
Date of Accident : 22/10/2022

Document No. : SQT22003120 **Page** 3
Date : 25. Oct 2022
Customer No. : WZF002
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : R16B25510614
Date | Time : 25. Oct 2022 11:51:53 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incl GST
BOJSE	BODY JOINT SEALANT FLOOR PANEL	1	100.00		100.00	7.00	107.00
BKRP02B	CUT & RENEW RR FLOOR PANEL STRAIGHTEN FENDERS ALIG	1	4500.00	26.00	4500.00	315.00	4815.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4000.00	26.00	4000.00	280.00	4280.00
Sum Labor					11060.00	774.20	11,834.20

Survey By

Date & Time

Excess

Status

Signature

Total Amount 16,136.93 1,129.59 17,266.52

Total (Inclusive of GST) 17,266.52

8 Days.
Before paint photos
E

LKK Auto Consultants hereby certify the Repair Estimate.

- This estimate is valid for 30 days from the date of issue.
- It is based on the information provided by the customer and the visual inspection of the vehicle.
- The actual cost of repair may vary due to the complexity of the work and the availability of parts.
- The customer is advised to obtain a second opinion from another qualified repairer.
- The customer is advised to keep the vehicle in a safe place until the repair is completed.

Accepted by the Repairer:

Signature:

Date:

Printed on 26/10/2022 10:48:29 AM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn Bhd, it will be refunded

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.