



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22010652/Ecy3e2 Date: 25/11/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHF 188R	Veh. Inspected	SMS 8004H	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/10/22/2075	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	27/10/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY	c.c	2487	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	JTNB23HK003054242	Colour	WHITE	
Odometer	54119 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	MICHELIN	5 mm	
L/H Front Tyre	215/55 R17	MICHELIN	5 mm	
R/H Rear Tyre	215/55 R17	MICHELIN	5 mm	
L/H Rear Tyre	215/55 R17	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/10/2022	Inspection Date	27/10/2022	
Survey held at	ACCORD AUTO SERVICES PTE LTD BLK 1009 BUKIT MERAH LANE 3 #01-80 SINGAPORE 159723			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	