

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT ALLIANZ INSURANCE SINGAPORE PTE LTD CS3/AIS22010653/Ecy3m4 Ref: 79 ROBINSON ROAD Date: 22/11/2022 #09-01 SINGAPORE 068897 Code: AIS 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SKP 9893R SLJ 2484D Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. 2022 22007641FR Excess (\$) 0.00 SHANTI 26/10/2022 Assign From Assign Date **Vehicle Particulars & Condition** 2. **VOLKSWAGEN GOLF** Make & Model 1395 C.C HIDDEN 2016 Engine No. Year of Reg. WVWZZZAUZHW049373 WHITE Chassis No. Colour Odometer 113460 KM Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 215/50 R17 DUNLOP 5 mm L/H Front Tyre 215/50 R17 DUNLOP 5 mm 215/50 R17 DUNLOP R/H Rear Tyre 5 mm DUNLOP L/H Rear Tyre 215/50 R17 5 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 21/10/2022 27/10/2022 (04:41 PM) Inspect Date / Time Accident Date T L S AUTO ENGINEERING PTE LTD Survey held at BLK 1010 BUKIT MERAH LANE 3 #01-13 SINGAPORE 159724 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

Report Ref No. CS3/AIS22010653/Ecy3m4

Estimate Days of Repair

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

CHEN TSUE YEE

CHEN TSUE YEE
Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

5 Working Days