

Name & Address:

LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00, SHAW TOWER
SINGAPORE 189702

Vehicle No:

SLW9324T

Date:

27-Oct-22

Brand & Model:

MAZDA 5

Franchise:

Mazda

Email/Fax No:

Contact No:

Chassis/VIN No:

JM6BN22A8J0209875

Contact Person (Eurokars)/Wip No:

JESS / 34447

Type of Claim:

THIRD PARTY

Policy No:

Date Of Registration:

09/03/2018

Contact No (Eurokars):

6331 0680

PARTS / MATERIAL CHARGES							MARK = Survey Marking [Key "A" if item is approved]	
NO	DESCRIPTION	PART NO.	UNIT PRICE	QTY	MARK	REVISED	PRICE	
1	REAR DOOR LH <i>front / DP</i>	MBJY0-73-02XF1	1,228.97	1		-	1,228.97	1,075.41
2	WEATHERSTRIP DOOR REAR LH <i>X NN</i>	MBHN9-73-760C	129.30	1		-		129.30
3	FASTENER(L), WEATHERS <i>/</i>	MBHN9-73-762	4.05	1		-		✓ 4.05
4	FASTENER <i>/</i>	MBC1D-58-762	2.70	10		-		✓ 27.00
5	GROMMET, SCREW <i>/</i>	MGJ6A-58-975	2.36	12		-		✓ 28.32
6	CLIP <i>/</i>	MGS1D-58-315A	2.36	1		-		✓ 2.36
7	GROMMET, SCREW <i>/</i>	M9991-00-503	2.36	1		-		✓ 2.36
8	FASTENER <i>/</i>	MGJ6A-68-AB1	3.71	5		-		✓ 18.55
9	GARNISH REAR DOOR LH <i>front /</i>	MBHS2-50-M20A	72.41	1		-		✓ 72.41
10	CLIP, GARNISH <i>/</i>	MKD53-50-M38	11.13	6		-		✓ 66.78
11	BODY SIDE MIRROR LH <i>/ CAA</i>	MB63B-69-181A	457.42	1		-		✓ 457.42
12	COVER SIDE MIRROR LH <i>X Repm</i>	MB63B-69-1N7 PR	130.98	1		-		130.98
13	LAMP SIDE TURN LH MIRROR <i>X / NN</i>	MB63B-69-182A	119.35	1		-		119.35
14	GLASS & HOLDER(L) <i>X</i>	MB63B-69-1G7	60.94	1		-		60.94
15	GARNISH(L), SAIL-OUT (TRIANGLE) <i>/ NEC</i>	MBHS2-69-16YB	26.47	1		-		✓ 26.47
16			-					-
Sub-Total (Parts Price)							-	2,221.70

LABOUR / SERVICES CHARGES			REVISED	PRICE
NO	DESCRIPTION			
1	TO REPLACE FRONT DOOR LH AND SIDE MIRROR LH.		✓ 660	800.00
2	TO RESPRAY FRONT DOOR LH AND COVER SIDE MIRROR LH.		✓ 630	1,000.00
3	TO TRANSFER FRONT LH DOOR MECHANISMS.	<i>NN</i>	NETT	X 330.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		✓ 150	250.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		✓ 180	300.00
6	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOU).	<i>NN</i>		X 250.00
7	SUNDRIES.		✓ 10	50.00

Survey Date & Time:

Repair Days:

Excess:

Sub-Total (Labour Price)

-

2,980.00

Surveyor Remarks:

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

	<u>REVISED</u>	<u>PRICE</u>
Parts Price	-	2,221.70
Labour Price	-	2,980.00
Total (Initial Estimate)	-	5,201.70
Supp 1	-	-
Supp 2	-	-
Supp 3	-	-
Total (Before Excess)	-	5,201.70
Less Excess	-	-
TOTAL (After Excess)	-	5,201.70
GST 7%	-	364.12
GRAND TOTAL	-	5,565.82

3 Days.
before paint photos.
Guo Qianf
82880282
1/11/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To do not touch the car body after resurvey
- To do not touch the car body after resurvey
- To do not touch the car body after resurvey
- To do not touch the car body after resurvey
- To do not touch the car body after resurvey
- To do not touch the car body after resurvey
- To do not touch the car body after resurvey
- To do not touch the car body after resurvey
- To do not touch the car body after resurvey

Acknowledged by:

Signature:

Date: