

HUA MENG SPRAY PAINTING WORKSHOP

LKK Auto Consultants hence notify

the Repairer of the **1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883**

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to cost of materials

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supply of original part(s) must be resurveyed and

is subject to final approval from Insurance Company

Vehicle No : **SLB 8890 S**

Chassis No: **RU11107588**

Acknowledged by Repairer

Autobay @ Kaki Bukit

Tel: **6747 8064, 6746 5519 / 9666 9680** Fax: **6743 4896**

ESTIMATE

Make/Model : **HONDA VEZEL**

Accident date : **23.10.2022**

TP Liberty
Veron.

No	Description	Qty	Amount (\$)
1	Rear windscreen rubber <i>new</i>	1	\$ 168.30 ✓
2	Rear tailgate <i>Distorted</i>	1	\$ 1,360.00 ✓
3	Rear tailgate hinges @ \$60.50 <i>new</i>	2	\$ 121.00 X
4	Rear tailgate upper lock <i>new</i>	1	\$ 221.10 165 X
5	Rear tailgate lower lock <i>new</i>	1	\$ 71.50 X
6	Rear tailgate shock absorber @ \$198.00 <i>new</i>	2	\$ 396.00 X
7	Rear tailgate inner board <i>cracked</i>	1	\$ 231.00 ✓
8	Rear tailgate reflector @ \$15.00 <i>RH cut</i>	2	\$ 30 415 ✓
9	Rear tailgate "H" emblem <i>new</i>	1	\$ 38.50 X
10	Rear tailgate "Vezel" emblem <i>new</i>	1	\$ 38.50 ✓
11	Rear tailgate weather strip <i>cut</i>	1	\$ 106.70 ✓
12	Rear end panel <i>Distorted</i>	1	\$ 457.60 ✓
13	Rear end panel inner top garnish <i>Distorted</i>	1	\$ 82.50 ✓
14	Rear lamp @ \$461.00 <i>RH cut</i>	2	\$ 922.00 461 X
15	Rear RH lamp lower garnish <i>new</i>	1	\$ 198.00 X
16	Rear bumper <i>Distorted</i>	1	\$ 858.00 745 ✓
17	Rear RH fender inner garnish @ \$418.00 <i>Distorted</i>	2	\$ 836.00 298 X
18	Rear RH fender side garnish <i>Distorted</i>	1	\$ 341.00 168 X
19	Rear spare tyre top board <i>new</i>	1	\$ 319.00 X
20	Rear spare tyre well <i>new</i>	1	\$ 858.00 X
			\$ 8,054.70 8454.70
			\$ 1,610.94
Total			\$ 6,443.76 6763.76

Special Nett Items

1	Rear bumper reverse sensor (1 set) <i>Distorted</i>	1	\$ 380.00 20
2	Rear bumper clips (1 set) <i>new</i>	1	\$ 60.00 30
Rear RH Fender Inner Garnish Clips <i>50</i> 30 Total <i>nec</i>			\$ 440.00
Rear RH Fender Side Garnish Clips <i>50</i> 20 <i>nec</i>			\$ 310
Labour Cost Tailgate Inner Trim Board Clips <i>50</i> 30 <i>nec</i>			

1	To supply rear end panel inner sealant		\$ 150.00 -60
2	To supply rear windscreen sealant		\$ 50.00 ✓
3	Remove & reinstall rear windscreen		\$ 150.00 120
4	Remove & reinstall reverse sensor		\$ 150.00 50
5	Remove & reinstall camera		\$ 100.00 50
6	Remove & reinstall bootlid inner garnish		\$ 200.00 60
7	Remove, replace & repair consistent to the accident		\$ 1,500.00 80
8	Respray painting		\$ 1,200.00 80
9	Tuff kote		\$ 100.00 60
Total			\$ 3,600.00

10 Remove and reinstall upholstery *150* 80

Grand Total

\$ 10,483.76 11,103.76

4.8K

Total 5989.28
C/S : 4.8K 06 Days