

GBF3518Z. 2016 Spt. 7PAXA.

Toyota Dyna. 2982cc

Xiao Tony.

JTFAT35Y80K206769.

|   |              |                 |
|---|--------------|-----------------|
| Front Bumper                            | Dented       | 683.80. ✓       |
| Front Bumper Bracket.                   | NP<br>m      | 316.40. ✕       |
| Headlamp RH.                            | Crushed      | 831.50. ✓       |
| Front RH Door                           | Dented       | 1485.10. ✓      |
| Front RH Door Lock                      | 2<br>NP<br>m | 375.90. ✕       |
| Front RH Door Weatherstripe             |              | 228.10. ✕       |
| Front RH Door Hinge x 02.               | NP<br>m      | 56 x 2 = 112. ✕ |
| Front RH Door Inner Trim Board.         | NP<br>m      | 598.20. ✕       |
| Front RH Door Inner Trim Board clips.   | NP<br>m      | 30(SW). ✕       |
| Front RH Door Company Address Stickers. | NP<br>m      | 30(SW). ✓       |
| Front RH Step Panel Garnish.            | Lot          | 289.80. ✓       |

GBF 3518Z.

Front RH Wheel Mudflap. Ut 186.70 ✓

Side Gate RH [redacted] Dented 1645.20 ✓

Side Gate Lower Step Panel RH. Dented 128.40 ✓

Side Gate Lower Step Panel Stopper RH. Missing 35.80 ✓

Side Gate Advertisement Sticker <sup>280(SN)</sup> ~~400(SN)~~ ✓

Rear RH Wheel Panel (Front) } Dented 250.40 ✓

Rear RH Wheel Panel (Rear) } Dented 250.40 ✓

Rear RH Stopper Missing 35.90 ✓

Rear RH Stopper Panel Bent 110.40 ✓

5933-50

445012

S.N: 310

GBF 3518Z.

Panel Beating

~~800~~ 700

Spray Painting.

~~800~~ 750

Wiring.

~~50~~ 30

1620

~~180~~ 60

To spray buff coat

~~150~~ 80.

To transfer front door fittings

total: 6380.12

L/S: 51K.

05 Days

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: