

Kg

Not Notional
 1/18000
 Resurvey After Paint
 3 days

		THIAM HENG HUAT PTE LTD	
		176 SIN MING DR #05-14	
		SINGAPORE 575721	
		ATT: STEVEN HP 82636295	
VEH NO:	SKQ 706C		
MODEL:	2015 VW GOLF 1.4		
CHASSIS:	WVWZZZAUZEW379461		
DOA:			
1PC REAR BUMPER ASSY	1012.00	Per / mfg cost	\$1,450.00 ✓
1PC REAR BUMPER LOWER GARNISH	573.10	nd / wt	\$ 580.00 ✓
1SET REAR BUMPER CLIPS		na	\$ 80.00 ✓
1PC REAR BUMPER CENTRE RETAINER		Per	\$ 130.00 X
2PC REAR BUMPER SIDE RETAINERS		Per	\$ 260.00 X
2PC REAR BUMPER REFLECTORS		Per	\$ 360.00 X
1PC REAR BUMPER REINFORCEMENT		R	\$ 680.00 X
2PC REAR NUMBER PLATE LAMPS		Per	\$ 120.00 X
1PC REAR BOOT ASSY		R	\$3,000.00 X
1PC REAR BOOT LOGO		na	\$ 180.00 X
1PC REAR BOOT LOCK		R	\$ 269.00 X
1PC REAR BOOT EMBLEM " GOLF "	90.80	mc	\$ 150.00 ✓
1PC REAR BOOT EMBLEM " T SKQ "		na	\$ 120.00 ✓
1PC REAR END PANEL		R	\$ 750.00 X
		Total	\$8,129.00
		Less 10%	\$7,316.10
		S/N	
1SET REVERSE SENSOR		Per	\$ 200.00 X
1PC REAR NUMBER PLATE		Per	\$ 100.00 X
		Labour	
PANEL BEATING			\$ 800.00 3000
PAINTING			\$ 800.00 4000
ANTI RUST		na	\$ 100.00 X
		Grand Total	\$9,316.10

SKQ Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: