

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122010669/ACY3Q2**Date:** 05/04/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMM6834Z**Insured Vehicle No :** YN1679R

Date of Loss: 21/10/2022

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMM6834Z**

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A)

Engine No: HIDDEN

Reg. Date: 01/07/2019 (Man. Year: 2019)

Chassis No: MMBSTA13AKH001444

Colour: Black

Odometer: 58289 km

Engine Capacity: 1193 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15

Rear Tyre Size:

185/55 R15

Front Left Side: Sailwin 6 mm

Rear Left Side:

Sailwin 6 mm

Front Right Side: Sailwin 6 mm

Rear Right Side:

Sailwin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,347.90	2,297.88	3,050.02	57.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	1,380.00	300.00	17.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,027.90	3,677.88	3,350.02	47.67
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	7,027.90	2,900.00	4,127.90	58.74
+ GST 8.00/8.00% (S\$)	562.23	232.00	330.23	58.74
Nett Amount (S\$)	7,590.13	3,132.00	4,458.13	58.74

INSPECTION

Date of Assignment: 26/10/2022

Date Inspected: 26/10/2022 Inspected At:

Green Forest Automobile Pte Ltd (Kaki Bukit)
8 Kaki Bukit Avenue 4, #05-25,, Premier@Kaki
Bukit
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 04 Apr 2023)	
Parts:	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM6834Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID CC LOGO	Not Necessary	35.00 F	*- FL
2	1		*REAR TAIL LAMP -RH	Cracked	551.20 F	*335.00 FL
3	4		*REAR TAIL LAMP CLIPS -RH	Not Necessary	32.00 F	*- FL
4	1		*REAR TAIL LAMP PANEL-RH	Distorted	211.00 F	*135.00 FL
5	1		*REAR BUMPER	Deformed	775.00 F	*775.00 FL
6	1		*REAR BUMPER SIDE BRACKET	O/S Damaged	244.00 F	*38.00 FL
7	1		*REAR BUMPER SIDE REFLECTOR -RH	Not Necessary	82.10 F	*- FL
8	1		*SET REAR BUMPER CLIPS	Necessary	65.00 F	*30.00 FL
9	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	350.00 F	*- FL
10	1		*REAR FENDER INNER TRIM BOARD RH	Not Necessary	385.20 F	*- FL
11	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	65.00 F	*- FL
12	1		*REAR FENDER -RH	Distorted	855.00 F	*855.00 FL
13	1		*REAR FENDER AIR DUCT	Not Necessary	78.20 F	*- FL
14	1		*REAR FENDER INNER PANEL -RH	Repair	322.00 F	*- FL
15	1		*REAR TYRE -RH	Punctured	350.00 FS	*180.00 FS
16	1		*REAR RIM -RH	Not Necessary	450.00 F	*- FL
17	1		*REAR LOWER ARM -RH	Not Necessary	312.00 F	*- FL
18	1		*REAR WHEEL BEARING -RH	Damaged	185.20 F	*185.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,347.90	2,533.20
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	235.32
Total Parts (\$\$)	5,347.90	2,297.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX CUSHION	New	120.00	60.00
2	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
3	TUFF KOTE	New	60.00	60.00
4	WHEEL ALIGNMENT (COMPUTER)	New	120.00	80.00
5	TO CHECK WIRING	New	60.00	30.00
6	PANEL BEATING	New	600.00	600.00
7	SPRAY PAINTING	New	600.00	500.00
Gross Labour Cost (S\$)			1,680.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >