

Vehicle Damage Assessment Report for [SMM6834Z]

Estimate Created: 24/03/2023 12:45 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 24/03/2023 13:00 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	Ergo	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Mitsubishi	Model	Attrage
Engine Type			
License Plate Number	SMM6834Z	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASED ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$2,900.00 WITH 5 WORKING
DAYS

Insurlogic 4 (24/03/2023 13:00)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
RH rear taillamp		1	335.00	-10.00 %	301.50
RH rear tail lamp panel		1	135.00	-10.00 %	121.50
Rear bumper		1	775.00	-10.00 %	697.50
Rear bumper side bracket		1	38.00	-10.00 %	34.20
Rear bumper clips (set)		1	30.00	-10.00 %	27.00
RH rear fender		1	855.00	-10.00 %	769.50
RH rear wheel bearing		1	185.20	-10.00 %	166.68

Parts Subtotal 2,117.88

Materials

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
RH rear tyre		1.0	180.00	0.00 %	180.00

Materials Subtotal 180.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
To remove and refix cushion.	RnR	60.00	0.00 %	60.00
To remove and refix reverse sensor	RnR	50.00	0.00 %	50.00
Tuff kote	RnR	60.00	0.00 %	60.00
Wheel alignment (computer)	RnR	80.00	0.00 %	80.00
To check wiring	RnR	30.00	0.00 %	30.00
Panel beating	RnR	600.00	0.00 %	600.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	500.00	0.00 %	500.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 880.00

Paint Labor Subtotal 500.00

Labor Subtotal 1,380.00

Summary

Repair Cost 3,677.88

Discount(20 %)	(735.58)
	2,942.30
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	2,942.30