

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0919/2022/EQ
DATE : 22-Oct-22
WIP : 47165

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 26/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR DESMOND LOH CHEE WAI
ADDRESS : 806 THOMSON ROAD
#15-15
SINGAPORE 298189
TELEPHONE : HP +65 96397184
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100511001-05
VEHICLE NO : **SCZ 8781 D**
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI QU
MODEL YEAR : 20/7/2017
ENGINE NO : DAX 007463
CHASSIS NO : WAUZZZFY1H2030930
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Oct-22
PLACE OF ACCIDENT : JUNCTION OF BALESTIER ROAD
& KIM KEAT ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCZ 8781 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	✓
2	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM, AND LHS WING MIRROR ASSY.	S/N \$	280.00	✓
3	TO REMOVE AND TRANSFER LHS HEADLIGHT'S POWER MODULE AND CONTROL UNIT.	S/N \$	480.00	250
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	1000
5	TO RESPRAY FRONT BUMPER, LOWER SPOILER, LHS FRONT FENDER, LHS FRONT DOOR AND BOTH FRONT WHEEL ARCH TRIMS.	\$	3,800.00	Bumper 550 spoiler 350 Fender 550
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	Wheel Arc x 2 = 400 Door 550
TOTAL LABOUR CHARGES		:	\$ 7,632.00	<u>2400</u>

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCZ 8781 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$ 1,789.00	✓
2	FRONT BUMPER SPOILER <i>Dehnd</i>	1	\$ 850.00	✓
3	RADIATOR GRILLE ?	1	\$ 3,910.00	?
4	FRONT BUMPER CLOSING ELEMENT - LH ?	1	\$ 126.00	?
5	FRONT BUMPER SECURING STRIP - LH ?	1	\$ 42.00	?
6	FRONT BUMPER UNDERRUN BAR <i>new</i>	1	\$ 580.00	+
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Dehnd</i>	1	\$ 651.00	✓
8	FRONT BUMPER END CAP - LH ?	1	\$ 103.00	?
9	FRONT PARKING AID SENSOR - OUTER <i>new</i>	1	\$ 266.00	+
10	FRONT PARKING AID SEAL RING <i>new</i>	10	\$ 25.00	+
11	FRONT BUMPER GUIDE SECTION - LH ?	1	\$ 43.00	?
12	FRONT FENDER - LH <i>Distorted</i>	1	\$ 1,462.00	✓
13	FRONT FENDER BRACE - LH ?	1	\$ 250.00	?
14	FRONT WHEEL SPOILER <i>3 new new</i>	1	\$ 181.00	+
15	FRONT WHEEL HOUSING LINER - LH	1	\$ 303.00	+
16	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 40.00	+
17	FRONT WHEEL COVER - LH / RH <i>new</i>	2	\$ 1,418.00	✓
18	HEADLIGHT - LH <i>cracked</i>	1	\$ 8,708.00	✓
19	LIFT CYLINDER - LH ?	1	\$ 153.00	?
20	HEADLIGHT MOUNTING - LH ?	1	\$ 132.00	?
SUB TOTAL SPARE PARTS		:	\$ 21,032.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCZ 8781 D

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT NO PLATE ?	S/N	\$ 60.00	?
22	SUNDRIES ?		\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 21,392.00	
TOTAL LABOUR CHARGES		:	\$ 7,632.00	
GRAND TOTAL		:	\$ 29,024.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

SURVEYED DATE

:

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Adrian Ling.
26/10/22

Not Authorised, 0 5 Days

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT