

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0921/2022/EQ
DATE : 25-Oct-22
WIP : 46732

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 26/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS YAN JIE
ADDRESS : 194 OCEAN DIRVE
SINGAPORE 098610

TELEPHONE : HP +65 91866770
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100490068-02
VEHICLE NO : **SLH 9764 K**
MODEL CODE : AUDI Q7 2.0 TFSI QU
MODEL YEAR : 24/11/2016
ENGINE NO : CYR 019949
CHASSIS NO : WAUZZZ4M0HD008373
MILEAGE : 18,105
DATE IN : 25-Oct-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Oct-22
PLACE OF ACCIDENT : MACPHERSON ROAD TOWARDS PAYA LEBAR

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLH 9764 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 900.00	720-
2	TO INSTALL SOLAR FILM FOR FRONT 1/4 GLASS.	S/N \$ 400.00	X.
3	TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,700.00	1200.
4	TO RESPRAY LHS FRONT DOOR, LHS WING MIRROR COVER, LHS REAR DOOR, 2 DOOR COVERS, DOOR HANDLE, LHS REAR DOOR WHEEL ARCH TRIM AND LHS REAR FENDER WHEEL ARCH TRIM.	\$ 4,500.00	1800. Door x 2 = 1200 Door Covers x 2 = 500 Door Arch 400.
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	1800-
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 8,972.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLH 9764 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT DOOR - LH <i>Dented</i>	1	\$ 5,466.00	✓	4372.80
2	FRONT OUTER DOOR SEAL <i>new</i>	1	\$ 282.00	✓	225.20
3	BONDING AGENT <i>new</i>	1	\$ 51.00	X	
4	CLEANING SOLUTION <i>new</i>	1	\$ 74.00	✓	58.96
5	APPLICATOR <i>new</i>	1	\$ 9.00	X	
6	FRONT DOOR CATCH - LH <i>new</i>	1	\$ 137.00	X	
7	FRONT DOOR COVER - LH <i>new</i>	1	\$ 734.00	✓	586.80
8	FRONT EXTERIOR WING MIRROR MOUNTING - LH <i>Cut</i>	1	\$ 1,664.00	✓	1331.20
9	FRONT WING MIRROR CAP - LH <i>new</i>	1	\$ 221.00	X	
10	FRONT WING MIRROR GLASS - LH <i>new chipped</i>	1	\$ 1,737.00	✓	1389.60
11	FRONT QUARTER WINDOW - LH <i>new cut</i>	1	\$ 291.00	✓	232.40
12	FRONT WINDOW GUIDE - LH <i>new</i>	1	\$ 560.00	X	
13	REAR DOOR - LH <i>Dented</i>	1	\$ 5,708.00	-	4566.40
14	REAR OUTER DOOR SEAL - LH <i>new</i>	1	\$ 278.00	✓	222.40
15	BONDING AGENT <i>new</i>	1	\$ 51.00	X	
16	CLEANING SOLUTION <i>new</i>	1	\$ 74.00	X	
17	APPLICATOR <i>new</i>	1	\$ 9.00	X	
18	REAR DOOR CATCH - LH <i>new</i>	1	\$ 137.00	X	
19	REAR OUTER DOOR SEAL - LH <i>new</i>	1	\$ 213.00	✓	170.40
20	REAR SILL PANEL SEAL - LH <i>new</i>	1	\$ 282.00	X	
SUB TOTAL SPARE PARTS		:	\$ 17,978.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLH 9764 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	REAR DOOR COVER - LH <i>Mer</i>	1	\$ 673.00	✓	538.40
22	REAR WHEEL COVER - LH <i>lit</i>	1	\$ 207.00	✓	165.20
23	REAR WHEEL COVER - LH <i>Mer</i>	1	\$ 397.00	X	
24	REAR ALUMINIUM RIM <i>lit</i>	1	\$ 2,266.00	✓	1812.80
25	REAR ALUMINIUM RIM RUBBER VALVE <i>At me New</i>	1	\$ 4.00	✓	2.96
26	SUNDRIES <i>Nec.</i>		\$ 500.00	✓	41.12
TOTAL SPARE PARTS		:	\$ 22,025.00		
TOTAL LABOUR CHARGES		:	\$ 8,972.00		
GRAND TOTAL		:	\$ 30,997.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian L
SURVEYED DATE : 26/10/22
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 05 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT