

**COMFORTDELGRO****ENGINEERING**

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

Our Job Ref No : 305533969  
Date : 28.10.2022

**FINALIZATION FORM**

To : LKK  
Attn : NAZ  
Vehicle Reg No. : SHC8600E

Fax :

Date of Accident : 23.10.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: INCOME --- SKT2567H
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \$411.00
  - (b) Labour Charges (include advertisement stickers etc,if any) \$630.00
  - Total for Part-By-Part Repair Cost** \$1,041.00
  - (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20%  
**Final Lumpsum Repair cost** \_\_\_\_\_
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : LIM T S  
Name : LIM T S  
Tel : 62148398  
Fax : 65468156

Signature : NAZ  
Name : NAZ  
Date : 28/10/2022

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00	Y		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 27.10.2022  
Time: 15:21:52  
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305533969  
REGN NO : SHC8600E  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G3)  
DATE OF REGN : 28.01.2021  
DATE/TIME IN : 25.10.2022 08:25  
ACCIDENT DATE : 23.10.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2533-G REAR BUMPER CTR MOULDING 1 451.25 20.00 361.00 / DEF  
0002 04-01-0104-1150-A REAR BUMPER MAT 1 50.00 50.00 / NEC

SUB-TOTAL : 411.00


JOB NATURE

0000 PB PANEL BEATING-SHC8600E-TP  
0001 SP SPRAYPAINT CHARGE  
0002 L R/I REVERSE SENSORS

350.00 /  
250.00 /  
30.00 /

SUB-TOTAL : 630.00

TOTAL : 1,041.00

  
MVA NAME & SIGNATURE  
DATE :

\_\_\_\_\_  
SURVEYOR NAME & SIGNATURE  
DATE : AUTHORIZED : YES / NO

**REPAIR ESTIMATE**DATE: 25.10.2022✓Police report  
(attached)INSURANCE: INCOME CP/PMODEL: Hyundai IoniqSURVEYOR: LKK-VEHICLE NO.: SHC8600EMVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$ 459.40
	Rear Bumper Centre Moulding	1		\$ 451.25
	Rear Bumper Lower Centre Moulding	1		\$ 155.00
	Rear Bumper Cover Clips	10	\$ 2.20	\$ 22.00
	Rear Bumper Reinforcement	1		\$ 394.80
	<b>SUB TOTAL</b>			\$ 1,482.45
	<b>LESS 20%</b>			\$ 296.49
	<b>DISCOUNTED TOTAL</b>			\$ 1,185.95
	Reverse Sensors	1		\$ 180.00
	<b>LESS 10%</b>			\$ 18.00
	<b>S/NETT TOTAL</b>	1		\$ 162.00
	Rear Bumper Mat	1		\$ 50.00
	<b>SPARE PARTS TOTAL</b>			\$ 1,397.96
	<b>Labour Charge</b>			\$ 400.00
	Panel Beating			\$ 300.00
	Spray Painting Charge			\$ 120.00
	Remove/Refix Reverse Sensor			
	<b>TOTAL LABOUR</b>			\$ 820.00
	<b>ESTIMATE TOTAL</b>			\$ 2,217.96

X R  
✓DEF  
? X SVC  
X SVC  
? X SVC

X SVC

NETT ✓NFC

350  
250  
30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKK

25/10/2022 1740 HRS

PIP

2 DAYS

CHECK ITEM PHOTOS

BEFORE PAINT PHOTOS

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: