

COMFORTDELGRO ENGINEERING PTE LTD

SAS-KIV

Effective Date: 1 Nov 2020

REPAIR ESTIMATEDATE: 25.10.2022INSURANCE: INCOME CL5MODEL: Hyundai IoniqSURVEYOR: LKK-VEHICLE NO.: SHD4909LMVA: JUMANI

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Rear Bumper	1		\$ 459.40	✓CRK
	Rear Bumper Centre Moulding	1		\$ 451.25	✓CRK
	Rear Bumper Lower Centre Moulding	1		\$ 155.00	?
	Rear Bumper Cover Clips	10	\$ 2.20	\$ 22.00	✓NFC
	Rear Bumper Reinforcement	1		\$ 394.80	?
	Rear Bumper Reflector RH	1		\$ 41.45	✓CRK
	Rear Bumper Side Udr Cvr RH	1		\$ 108.00	?
	Rear Fender RH	1		\$ 1,768.30	✓DD
	Rear Blind Spot Radar RH	1		\$ 1,784.40	?
	TailLamp RH	1		\$ 935.40	✓CRK
	SUB TOTAL			\$ 6,120.00	
	LESS 20%			\$ 1,224.00	
	DISCOUNTED TOTAL			\$ 4,896.00	
	Reverse Sensors	1		\$ 180.00	XSVL
	LESS 10%			\$ 18.00	
	S/NETT TOTAL	1		\$ 162.00	
	Rear Bumper Mat	1		\$ 50.00	NETT ✓NFC
	SPARE PARTS TOTAL			\$ 5,108.00	
	Labour Charge				
	Panel Beating			\$ 1,200.00	700
	Spray Painting Charge			\$ 900.00	500
	Remove/Refix Reverse Sensor			\$ 120.00	30
	Check Lightings			\$ 80.00	30
	Tuff Kote			\$ 100.00	40
	Diagnostic & Reset Rear Blind Spot Radar RH			\$ 350.00	?
	Towing Fee			-	
	TOTAL LABOUR			\$ 2,750.00	
	ESTIMATE TOTAL			\$ 7,858.00	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

My 2 LK
 25/10/2022 1720 HRS
 LIS
 3 Days
 CHECK ITEM PHOTOS
 AFTER REPAIR PHOTOS