

REPAIR ESTIMATEDATE: 25.10.2022INSURANCE: INCOME (45)MODEL: Hyundai IoniqSURVEYOR: LKK-VEHICLE NO.: SHD4909LMVA: JUMANI

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Rear Bumper	1		\$ 459.40	/CRK
	Rear Bumper Centre Moulding	1		\$ 451.25	/CRK
	Rear Bumper Lower Centre Moulding	1		\$ 155.00	? X SVC
	Rear Bumper Cover Clips	10	\$ 2.20	\$ 22.00	/NFC
	Rear Bumper Reinforcement	1		\$ 394.80	? X SVC
	Rear Bumper Reflector RH	1		\$ 41.45	/CRK
	Rear Bumper Side Udr Cvr RH	1		\$ 108.00	? X SVC
	Rear Fender RH	1		\$ 1,768.30	/DD
	Rear Blind Spot Radar RH	1		\$ 1,784.40	? X SVC
	TailLamp RH	1		\$ 935.40	/CRK
	SUB TOTAL			\$ 6,120.00	
	LESS 20%			\$ 1,224.00	
	DISCOUNTED TOTAL			\$ 4,896.00	
	Reverse Sensors	1		\$ 180.00	X SVC
	LESS 10%			\$ 18.00	
	S/NETT TOTAL	1		\$ 162.00	
	Rear Bumper Mat	1		\$ 50.00	NETT /NFC
	SPARE PARTS TOTAL			\$ 5,108.00	
	<u>Labour Charge</u>				
	Panel Beating			\$ 1,200.00	700
	Spray Painting Charge			\$ 900.00	500
	Remove/Refix Reverse Sensor			\$ 120.00	30
	Check Lightings			\$ 80.00	30
	Tuff Kote			\$ 100.00	40
	Diagnostic & Reset Rear Blind Spot Radar RH			\$ 350.00	? X NN
	Towing Fee			-	
	TOTAL LABOUR			\$ 2,750.00	
	ESTIMATE TOTAL			\$ 7,858.00	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKK
25/10/2022 1720 HRS
LIS
3 Days
CHECK ITEM PHOTO
AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: